Register entry, as of 26 October 2026 Listed for sale Record ID 9e860739f7bc

2021 Kia Seltos SX

1.6 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KND	ETCA2	0	M	7	058637
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Kia Corporation	Seltos · 1.6 L	Computes	2021	Gwang-Ju	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	1.6 L, 4 cylinders
Make	Kia	Fuel	Gasoline
Model	Seltos	Drive	4WD
Trim	SX	Maker	KIA CORPORATION
Body	Sport Utility Vehicle	Plant	Gwang-Ju, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/seltos/2021

4 recalls listed by Transport Canada for this model year

Engine

2025083 18 Feb 2025

Issue: On certain vehicles, the piston oil rings may not have been manufactured properly and could damage the cylinder walls. As a result, the engine could make abnormal noises, and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This recall only affects certain vehicles equipped with a 2.0L MPI engine. Safety Risk: An engine failure could cause a sudden loss of power to the wheels and/or increase the risk of a vehicle fire. Both issues could increase the risk of a crash or injury. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the engine. The dealer will also install a software that will monitor the engine and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange replacement of the engine.

Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

Electrical

2024093 14 Feb 2024

Issue: On certain vehicles, the 4WD control unit under the driver's seat may become contaminated by a mixture of salt and moisture inside the vehicle. Over time, this can lead to corrosion that could cause a short circuit. Note: This recall only affects vehicles equipped with all-wheel drive. Safety Risk: A short circuit can create a fire risk, even while the vehicle is parked and turned off. Corrective actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect the 4WD control unit. The control unit and other components will be replaced as necessary. The dealer will also install a protective cover over the 4WD control unit. Kia advises that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Engine

2021225 14 Apr 2021

Issue: On certain vehicles, the engine's piston oil rings may be defective. This can cause engine wear that can lead to increased oil consumption. Eventually, this can create abnormal engine noise and the oil pressure warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This only affects vehicles equipped with a 2.0 L Nu MPI engine. Safety Risk: A sudden loss of engine power could increase the risk of a crash. An engine failure could also create the risk of a fire. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the engine. The engine will be replaced, if necessary. The dealer will also install a Piston-ring Noise Sensing System (PNSS) software update, to alert the driver of potential damage before an engine failure occurs.

Listed for the model year, not checked against your VIN. Kia confirms which apply.
Check your VIN with Kia Canada or call a Kia dealer with your VIN.
www.kia.ca/en/owners/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $19,255[5], $2,660 under the median of $21,915[4].



Lowest ask	$14,888
Middle half	$19,477 – $22,998
Median ask	$21,915
This car	$19,255

Same configuration · 29 live listings · as of 26 Oct 2026

OTHER 2021 KIA SELTOS LISTINGS [5]

Rivière-du-Loup, QC · 101,046 km	$17,978
Georgetown, ON · 94,954 km	$20,105
Victoriaville, QC · 134,403 km	$16,495
Surrey, BC · 114,050 km	$20,900
Québec, QC · 114,852 km	$19,477
Québec, QC · 91,119 km	$18,977

§4 EVENTS

2021	Model year 2021[1] Assembly plant Gwang-Ju, South Korea
14 Apr 2021	Transport Canada recall 2021225[2] Issued for the model year · Engine
14 Feb 2024	Transport Canada recall 2024093[2] Issued for the model year · Electrical
15 Aug 2024	Transport Canada recall 2024549[2] Issued for the model year · Label
18 Feb 2025	Transport Canada recall 2025083[2] Issued for the model year · Engine

26 Oct 2026 **Listed for sale, Edmonton, AB**[5]
Lakewood Chevrolet · asking $19,255

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 29 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.