Register entry, as of 27 October 2026 Listed for sale Record ID fed8870f21c0

# 2021 Kia Soul EX

2.0 L, 4 cylinders · 4x2 · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| KND | J33AU | 6 | M | 7 | 764706 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Kia Corporation | Soul · 2.0 L | Computes | 2021 | Gwang-Ju | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2021 | Engine | 2.0 L, 4 cylinders |
| Make | Kia | Fuel | Gasoline |
| Model | Soul | Drive | 4x2 |
| Trim | EX | Maker | KIA CORPORATION |
| Body | Sport Utility Vehicle | Plant | Gwang-Ju, South Korea |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/soul/2021

**3** recalls listed by Transport Canada for this model year

### Engine

2025083 18 Feb 2025

Issue: On certain vehicles, the piston oil rings may not have been manufactured properly and could damage the cylinder walls. As a result, the engine could make abnormal noises, and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This recall only affects certain vehicles equipped with a 2.0L MPI engine. Safety Risk: An engine failure could cause a sudden loss of power to the wheels and/or increase the risk of a vehicle fire. Both issues could increase the risk of a crash or injury. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the engine. The dealer will also install a software that will monitor the engine and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange replacement of the engine.

### Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

### Engine

2021225 14 Apr 2021

Issue: On certain vehicles, the engine's piston oil rings may be defective. This can cause engine wear that can lead to increased oil consumption. Eventually, this can create abnormal engine noise and the oil pressure warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This only affects vehicles equipped with a 2.0 L Nu MPI engine. Safety Risk: A sudden loss of engine power could increase the risk of a crash. An engine failure could also create the risk of a fire. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the engine. The engine will be replaced, if necessary. The dealer will also install a Piston-ring Noise Sensing System (PNSS) software update, to alert the driver of potential damage before an engine failure occurs.

> Listed for the model year, not checked against your VIN. Kia confirms which apply.
> Check your VIN with Kia Canada or call a Kia dealer with your VIN.
> www.kia.ca/en/owners/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $15,990[5], the median[4].

| | |
|---|---|
| Lowest ask | $8,499 |
| Middle half | $15,446 – $17,722 |
| Median ask | $15,990 |
| This car | $15,990 |

Same configuration · 26 live listings · as of 27 Oct 2026

### OTHER 2021 KIA SOUL LISTINGS [5]

| | |
|---|---|
| Québec, QC · 45,959 km | $16,697 |
| Wilkie, SK · 122,095 km | $15,599 |
| Québec, QC · 45,959 km | $16,697 |
| St Marys, ON · 94,069 km | $15,795 |
| Courtenay, BC · 131,506 km | $15,195 |
| Mount Pearl, NL · 65,481 km | $17,995 |

## §4 EVENTS

| | |
|---|---|
| 2021 | Model year 2021[1]<br>Assembly plant Gwang-Ju, South Korea |
| 14 Apr 2021 | Transport Canada recall 2021225[2]<br>Issued for the model year · Engine |
| 15 Aug 2024 | Transport Canada recall 2024549[2]<br>Issued for the model year · Label |
| 18 Feb 2025 | Transport Canada recall 2025083[2]<br>Issued for the model year · Engine |
| 26 Oct 2026 | Listed for sale, Brossard, QC[5]<br>Mega Kia Brossard · asking $15,990 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $15,990 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 26 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.