Register entry, as of 27 October 2026 Listed for sale Record ID b392adbbea0e

# 2015 Kia Soul GLS(Middle grade)

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| KND | JP3A5 | 4 | F | 7 | 226201 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Kia Corporation | Soul · 2.0 L | Computes | 2015 | Gwangju | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2015 | Engine | 2.0 L, 4 cylinders |
| Make | Kia | Fuel | Gasoline |
| Model | Soul | Drive | Not in the decode |
| Trim | GLS(Middle grade) | Maker | KIA CORPORATION |
| Body | Sport Utility Vehicle | Plant | Gwangju, South Korea |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/soul/2015

**10** recalls listed by Transport Canada for this model year

### Brakes

2024760 13 Dec 2024

Issue: Over time, the brake lines under the vehicle could corrode. If this happens, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect the brake lines. The dealer will apply an anti-corrosion treatment and replace the brake lines, if required.

### Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

### Electrical

2024345 14 Jun 2024

Issue: On certain vehicles, the wiring for the heated seat could disconnect and cause the seat heaters to overheat. Safety Risk: A seat heater that overheats could create the risk of a burn injury. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace the seat heater electronic control unit. The dealer will also replace the seat heater pad(s), as necessary.

### Engine

2021204 6 Apr 2021

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure could cause a sudden loss of power with an inability to restart. Note: This campaign only affects vehicles equipped with a 1.6 L GDI engine. Safety Risk: A sudden loss of engine power could increase the risk of a crash. An engine failure could also create the risk of a fire. Corrective Actions: Kia will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Kia recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Kia advises you to immediately visit a Kia dealership to have your vehicle diagnosed.

### Engine

2020597 4 Dec 2020

Issue: On certain vehicles equipped with a 2.0 L NU GDI or 2.4 L Theta II MPI engine, an engine compartment fire could occur while driving. Kia is conducting this recall as a preventative measure to prevent fire risk due to potential fuel leaks, oil leaks and/or engine damage. In some situations, you may notice any of the following symptoms: there could be an abnormal knocking noise from the engine; the check engine light and/or the oil pressure warning light could turn on; you may smell fuel, burning or smoke; or you may notice oil leaks. If you continue to drive the vehicle with these symptoms, the engine could fail and/or a fire could occur. An engine failure can cause a sudden loss of power with an inability to restart. Note: For the Optima model, only the Optima Hybrid is affected by this recall. Safety Risk: An engine compartment fire can create a risk of injury. A sudden loss of engine power could increase the risk of a crash. Corrective Action: Kia will notify owners by mail and instruct you to take your vehicle to a dealer for an inspection of the engine and engine compartment. The dealer will inspect for fuel and/or engine oil leaks, perform an engine test and make any repairs, including engine replacement, if necessary. Kia will also perform a Knock Sensor Detection System (KSDS) software update free of charge, once it is available for your vehicle. This update will detect and prevent engine damage from worn connecting rod bearings.

### Engine

2020535 11 Nov 2020

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure may cause a sudden loss of power with an inability to restart. Note: This campaign affects vehicles with a 2.0 L GDI engine. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module.

4 more on the model-year record, cardog.app/tools/recalls/kia/soul/2015

> Listed for the model year, not checked against your VIN. Kia confirms which apply.
> Check your VIN with Kia Canada or call a Kia dealer with your VIN.
> www.kia.ca/en/owners/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $6,995[5], $1,593 under the median of $8,588[4].




| | |
|---|---|
| Lowest ask | $4,590 |
| Middle half | $6,698 – $9,738 |
| Median ask | $8,588 |
| This car | $6,995 |

Same configuration · 27 live listings · as of 27 Oct 2026

### OTHER 2015 KIA SOUL LISTINGS [5]

| | |
|---|---|
| London, ON · 262,626 km | $4,590 |
| Leduc, AB · 134,572 km | $10,803 |
| Surrey, BC · 92,370 km | $12,988 |
| Longueuil, QC · 156,745 km | $8,955 |

| | |
|---|---|
| Medicine Hat, AB · 228,939 km | $6,900 |
| Laval, QC · 136,800 km | $5,888 |

## §4 EVENTS

| | |
|---|---|
| 2015 | Model year 2015[1]<br>Assembly plant Gwangju, South Korea |
| 11 Mar 2015 | Transport Canada recall 2015102[2]<br>Issued for the model year · Powertrain |
| 12 Nov 2015 | Transport Canada recall 2015535[2]<br>Issued for the model year · Steering |
| 23 Oct 2017 | Transport Canada recall 2017514[2]<br>Issued for the model year · Steering |
| 28 Feb 2019 | Transport Canada recall 2019101[2]<br>Issued for the model year · Engine |
| 11 Nov 2020 | Transport Canada recall 2020535[2]<br>Issued for the model year · Engine |
| 4 Dec 2020 | Transport Canada recall 2020597[2]<br>Issued for the model year · Engine |
| 6 Apr 2021 | Transport Canada recall 2021204[2]<br>Issued for the model year · Engine |
| 14 Jun 2024 | Transport Canada recall 2024345[2]<br>Issued for the model year · Electrical |
| 15 Aug 2024 | Transport Canada recall 2024549[2]<br>Issued for the model year · Label |
| 13 Dec 2024 | Transport Canada recall 2024760[2]<br>Issued for the model year · Brakes |
| 12 May 2026 | Listed for sale, Barrie, ON[5]<br>Cars Canada · asking $6,995 |
| 26 Oct 2026 | Listing last updated[5]<br>asking $6,995 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We have not collected this label yet. |

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 27 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.