Register entry, as of 27 October 2026 Listed for sale Record ID 65cc94738e7f

2017 Kia Soul Plus

2.0 L, 4 cylinders · 4x2 · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KND	JP3A5	9	H	7	433833
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Kia Corporation	Soul · 2.0 L	Computes	2017	Gwang-Ju	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	2.0 L, 4 cylinders
Make	Kia	Fuel	Gasoline
Model	Soul	Drive	4x2
Trim	Plus	Maker	KIA CORPORATION
Body	Sport Utility Vehicle	Plant	Gwang-Ju, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/soul/2017

5 recalls listed by Transport Canada for this model year

Brakes

2024760 13 Dec 2024

Issue: Over time, the brake lines under the vehicle could corrode. If this happens, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect the brake lines. The dealer will apply an anti-corrosion treatment and replace the brake lines, if required.

Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

Electrical

2024345 14 Jun 2024

Issue: On certain vehicles, the wiring for the heated seat could disconnect and cause the seat heaters to overheat. Safety Risk: A seat heater that overheats could create the risk of a burn injury. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace the seat heater electronic control unit. The dealer will also replace the seat heater pad(s), as necessary.

Airbag

2022023 27 Jan 2022

Issue: On certain vehicles, a defect in the airbag control unit could cause the airbag warning light to turn on. If this happens, the airbag system may not work properly, and the airbags may not inflate in a crash. Safety Risk: An airbag system that does not work properly could create an increased risk of injury in a crash. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to update the airbag control unit software. If the airbag warning light is on because of diagnostic trouble code B1620, the dealer will replace the airbag control unit.

Engine

2021733 7 Dec 2021

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure could cause a sudden loss of power with an inability to restart. Note: This only affects vehicles equipped with a 2.0 L Nu GDI engine. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Kia will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Kia recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Kia advises you to immediately visit a Kia dealership to have your vehicle diagnosed.

Listed for the model year, not checked against your VIN. Kia confirms which apply.
Check your VIN with Kia Canada or call a Kia dealer with your VIN.
www.kia.ca/en/owners/recalls

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $10,495[5], $1,444 under the median of $11,939[4].

Lowest ask	$4,899
Middle half	$10,571 – $13,082
Median ask	$11,939
This car	$10,495

Same configuration · 14 live listings · as of 27 Oct 2026

OTHER 2017 KIA SOUL LISTINGS [5]

Edmonton, AB · 57,405 km	$14,995
Pitt Meadows, BC · 84,309 km	$16,695
Pitt Meadows, BC · 84,309 km	$16,695
Longueuil, QC · 157,945 km	$11,455
Calgary, AB · 87,823 km	$17,008
Sainte-Rose, QC · 115,007 km	$11,995

§4 EVENTS

2017	Model year 2017[1] Assembly plant Gwang-Ju, South Korea
7 Dec 2021	Transport Canada recall 2021733[2] Issued for the model year · Engine

27 Jan 2022	Transport Canada recall 2022023[2] Issued for the model year · Airbag
14 Jun 2024	Transport Canada recall 2024345[2] Issued for the model year · Electrical
15 Aug 2024	Transport Canada recall 2024549[2] Issued for the model year · Label
13 Dec 2024	Transport Canada recall 2024760[2] Issued for the model year · Brakes
25 Oct 2026	Listed for sale, Granby, QC[5] Hyundai Granby · asking $10,495

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 14 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.