

Register entry, as of 28 October 2026

Listed for sale

Record ID 4dde8f8ab44a

2011 Kia Soul GL

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KND JT2A2 7 B 7 334074

WMI 1-3

Kia Corporation

DESCRIPTOR 4-8

Soul · 2.0 L

CHECK 9

Computes

YEAR 10

2011

PLANT 11

Gwangju

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2011	Engine	2.0 L, 4 cylinders
Make	Kia	Fuel	Gasoline
Model	Soul	Drive	Not in the decode
Trim	GL	Maker	KIA CORPORATION
Body	Sport Utility Vehicle	Plant	Gwangju, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/soul/2011

5 recalls listed by Transport Canada for this model year

Label	2024549	15 Aug 2024
Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.		
Brakes	2023529	26 Sep 2023
Issue: On certain vehicles, the brake hydraulic electronic control unit (HECU) could short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse(s) for the HECU. Kia recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.		
Seats and restraints	2017469	28 Sep 2017
On certain vehicles equipped with heated cloth seats, over time, the wiring for the seat heater mats could become damaged. If a heating mat were to be damaged, it could melt a small hole in the lower portion of the seat base or backrest, which could result in injury to the seat occupant. Correction: Dealers will attach a patch on the seat cushion and seat back heater bridge side and adjust the positioning. If there are traces of burning or melting during the inspection, dealers will replace the heater with a new one and adjust the bridge wire side positioning.		
Airbag	2014591	23 Dec 2014
On certain vehicles equipped with sunroofs, headliner plates may detach from the headliner during a side curtain airbag deployment and could strike vehicle occupants. This could increase the risk of injury. Correction: Dealers will apply adhesive strips to the headliner plates.		



Brakes

2013098 3 Apr 2013


On certain vehicles, the stop lamp switch may fail and cause intermittent operation of the brake lights. Failure of the brake lights to illuminate when the brake pedal is depressed could result in a crash causing property damage and/or personal injury. Correction: Dealers will replace the switch.

Listed for the model year, not checked against your VIN. Kia confirms which apply.
Check your VIN with Kia Canada or call a Kia dealer with your VIN.
www.kia.ca/en/owners/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$5,995^[5], \$1,283 over the median of \$4,712^[4].



Lowest ask	\$3,450
Middle half	\$4,107 – \$5,741
Median ask	\$4,712
This car	\$5,995

Same model year · 6 live listings · as of 28 Oct 2026

OTHER 2011 KIA SOUL LISTINGS ^[5]

Port Alberni, BC · 204,698 km	\$4,980
Drummondville, QC · 188,000 km	\$3,995
Toronto, ON · 97,111 km	\$4,444
Charlesbourg, QC · 193,514 km	\$3,450
London, ON · 126,194 km	\$7,995

§4 EVENTS

2011	Model year 2011 ^[1] Assembly plant Gwangju, South Korea
3 Apr 2013	Transport Canada recall 2013098 ^[2] Issued for the model year · Brakes
23 Dec 2014	Transport Canada recall 2014591 ^[2] Issued for the model year · Airbag
28 Sep 2017	Transport Canada recall 2017469 ^[2] Issued for the model year · Seats and restraints
26 Sep 2023	Transport Canada recall 2023529 ^[2] Issued for the model year · Brakes
15 Aug 2024	Transport Canada recall 2024549 ^[2] Issued for the model year · Label



26 Oct 2026 Listed for sale, Trois-Rivières, QC^[5]
automobilesdenislefebvre.com · asking \$5,995

27 Oct 2026 Listing last updated^[5]
asking \$5,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- [1] Cardog identity register, decoded from the VIN
- [2] Transport Canada recall database, listed for the model year
- [3] NHTSA recall records (United States), listed for the model year
- [4] Cardog market quote, same model year, 6 live listings, as of 28 Oct 2026
- [5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

