Register entry, as of 29 October 2026 Listed for sale Record ID 4878820e8c1a

2014 Kia Soul TOP(EXCLAIM)

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KND	JX3A5	0	E	7	088302
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Kia Corporation	Soul · 2.0 L	Computes	2014	Gwangju	Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	2.0 L, 4 cylinders
Make	Kia	Fuel	Gasoline
Model	Soul	Drive	Not in the decode
Trim	TOP(EXCLAIM)	Maker	KIA CORPORATION
Body	Sport Utility Vehicle	Plant	Gwangju, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/soul/2014

12 recalls listed by Transport Canada for this model year

Brakes

2024760 13 Dec 2024

Issue: Over time, the brake lines under the vehicle could corrode. If this happens, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect the brake lines. The dealer will apply an anti-corrosion treatment and replace the brake lines, if required.

Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

Electrical

2024345 14 Jun 2024

Issue: On certain vehicles, the wiring for the heated seat could disconnect and cause the seat heaters to overheat. Safety Risk: A seat heater that overheats could create the risk of a burn injury. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace the seat heater electronic control unit. The dealer will also replace the seat heater pad(s), as necessary.

Airbag

2022077 21 Feb 2022

Issue: On certain vehicles, the front-impact sensors for the airbag system could be damaged in a severe crash. If this happens, the front airbags may not inflate. Safety Risk: Airbags that do not inflate in a crash could create an increased risk of injury. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to update the airbag control unit (ACU) software.

Engine

2021204 6 Apr 2021

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure could cause a sudden loss of power with an inability to restart. Note: This campaign only affects vehicles equipped with a 1.6 L GDI engine. Safety Risk: A sudden loss of engine power could increase the risk of a crash. An engine failure could also create the risk of a fire. Corrective Actions: Kia will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Kia recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Kia advises you to immediately visit a Kia dealership to have your vehicle diagnosed.

Engine

2020597 4 Dec 2020

Issue: On certain vehicles equipped with a 2.0 L NU GDI or 2.4 L Theta II MPI engine, an engine compartment fire could occur while driving. Kia is conducting this recall as a preventative measure to prevent fire risk due to potential fuel leaks, oil leaks and/or engine damage. In some situations, you may notice any of the following symptoms: there could be an abnormal knocking noise from the engine; the check engine light and/or the oil pressure warning light could turn on; you may smell fuel, burning or smoke; or you may notice oil leaks. If you continue to drive the vehicle with these symptoms, the engine could fail and/or a fire could occur. An engine failure can cause a sudden loss of power with an inability to restart. Note: For the Optima model, only the Optima Hybrid is affected by this recall. Safety Risk: An engine compartment fire can create a risk of injury. A sudden loss of engine power could increase the risk of a crash. Corrective Action: Kia will notify owners by mail and instruct you to take your vehicle to a dealer for an inspection of the engine and engine compartment. The dealer will inspect for fuel and/or engine oil leaks, perform an engine test and make any repairs, including engine replacement, if necessary. Kia will also perform a Knock Sensor Detection System (KSDS) software update free of charge, once it is available for your vehicle. This update will detect and prevent engine damage from worn connecting rod bearings.

6 more on the model-year record, cardog.app/tools/recalls/kia/soul/2014

> Listed for the model year, not checked against your VIN. Kia confirms which apply.
> Check your VIN with Kia Canada or call a Kia dealer with your VIN.
> www.kia.ca/en/owners/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $7,995[5], $500 under the median of $8,495[4].



Lowest ask	$4,499
Middle half	$6,745 – $8,999
Median ask	$8,495
This car	$7,995

Same model year · 15 live listings · as of 29 Oct 2026

OTHER 2014 KIA SOUL LISTINGS [5]

Edmonton, AB · 101,145 km	$11,995
Courtenay, BC · 106,881 km	$8,495
Laval, QC · 190,000 km	$4,499
Beloeil, QC · 212,877 km	$6,995
Lasalle, QC · 39,520 km	$8,999
London, ON · 35,325 km	$12,495

§4 EVENTS

2014	Model year 2014[1] Assembly plant Gwangju, South Korea
19 Jun 2014	Transport Canada recall 2014237[2] Issued for the model year · Steering
11 Mar 2015	Transport Canada recall 2015102[2] Issued for the model year · Powertrain
12 Nov 2015	Transport Canada recall 2015535[2] Issued for the model year · Steering
23 Oct 2017	Transport Canada recall 2017514[2] Issued for the model year · Steering
28 Feb 2019	Transport Canada recall 2019101[2] Issued for the model year · Engine
11 Nov 2020	Transport Canada recall 2020535[2] Issued for the model year · Engine
4 Dec 2020	Transport Canada recall 2020597[2] Issued for the model year · Engine
6 Apr 2021	Transport Canada recall 2021204[2] Issued for the model year · Engine
21 Feb 2022	Transport Canada recall 2022077[2] Issued for the model year · Airbag
14 Jun 2024	Transport Canada recall 2024345[2] Issued for the model year · Electrical
15 Aug 2024	Transport Canada recall 2024549[2] Issued for the model year · Label
13 Dec 2024	Transport Canada recall 2024760[2] Issued for the model year · Brakes
25 Oct 2026	Listed for sale, London, ON[5] Tiger Auto Sales Ltd. · asking $7,995
29 Oct 2026	Listing last updated[5] asking $7,995

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 15 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.