Register entry, as of 27 November 2026 Listed for sale Record ID 8f51b23747b2

2016 Kia Soul

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KND	JX3A5	9	G	7	825838
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Kia Corporation	Soul · 2.0 L	Computes	2016	Gwangju	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	2.0 L, 4 cylinders
Make	Kia	Fuel	Gasoline
Model	Soul	Drive	Not in the decode
Trim	Not in the decode	Maker	KIA CORPORATION
Body	Sport Utility Vehicle	Plant	Gwangju, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/soul/2016

8 recalls listed by Transport Canada for this model year

Brakes — 2024760 — 13 Dec 2024

Issue: Over time, the brake lines under the vehicle could corrode. If this happens, a brake line could fail and leak. A brake fluid leak can result in reduced braking. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect the brake lines. The dealer will apply an anti-corrosion treatment and replace the brake lines, if required.

Label — 2024549 — 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

Electrical — 2024345 — 14 Jun 2024

Issue: On certain vehicles, the wiring for the heated seat could disconnect and cause the seat heaters to overheat. Safety Risk: A seat heater that overheats could create the risk of a burn injury. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace the seat heater electronic control unit. The dealer will also replace the seat heater pad(s), as necessary.

Engine

2021204 6 Apr 2021

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure could cause a sudden loss of power with an inability to restart. Note: This campaign only affects vehicles equipped with a 1.6 L GDI engine. Safety Risk: A sudden loss of engine power could increase the risk of a crash. An engine failure could also create the risk of a fire. Corrective Actions: Kia will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Kia recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Kia advises you to immediately visit a Kia dealership to have your vehicle diagnosed.

Engine

2020535 11 Nov 2020

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure may cause a sudden loss of power with an inability to restart. Note: This campaign affects vehicles with a 2.0 L GDI engine. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module.

Engine

2019101 28 Feb 2019

Issue: On certain vehicles, the catalytic converter may be damaged by overheating. This could also cause engine damage or an engine failure. An engine failure would cause a sudden loss of power with an inability to restart. Safety Risk: A sudden loss of engine power could increase the risk of a crash. An engine failure may also result in a fire. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have the engine software updated. This update will prevent overheating of the catalytic converter. Vehicles will also be inspected for other damage. Depending on the results of the inspection, the catalytic converter and/or the engine may be replaced. Note: A driver may notice any of the following symptoms of this problem: a knocking sound from the engine, reduced power or hesitation, and/or the illumination of the Malfunction Indicator Lamp (MIL) or check engine light.

2 more on the model-year record, cardog.app/tools/recalls/kia/soul/2016

> Listed for the model year, not checked against your VIN. Kia confirms which apply.
> Check your VIN with Kia Canada or call a Kia dealer with your VIN.
> www.kia.ca/en/owners/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $8,980[5], $910 under the median of $9,890[4].



Lowest ask	$5,975
Middle half	$8,980 – $10,299
Median ask	$9,890
This car	$8,980

Same configuration · 13 live listings · as of 27 Nov 2026

OTHER 2016 KIA SOUL LISTINGS [5]

Mirabel, QC · 61,000 km	$12,786
Charlottetown, PE · 95,475 km	$6,500
North Vancouver, BC · 136,983 km	$9,495
Victoria, BC · 69,291 km	$9,931
Edmonton, AB · 152,775 km	$7,888
Waterloo, ON · 166,557 km	$7,572

§4 EVENTS

2016	Model year 2016[1] Assembly plant Gwangju, South Korea
12 Nov 2015	Transport Canada recall 2015535[2] Issued for the model year · Steering
23 Oct 2017	Transport Canada recall 2017514[2] Issued for the model year · Steering
28 Feb 2019	Transport Canada recall 2019101[2] Issued for the model year · Engine
11 Nov 2020	Transport Canada recall 2020535[2] Issued for the model year · Engine
6 Apr 2021	Transport Canada recall 2021204[2] Issued for the model year · Engine
14 Jun 2024	Transport Canada recall 2024345[2] Issued for the model year · Electrical
15 Aug 2024	Transport Canada recall 2024549[2] Issued for the model year · Label
13 Dec 2024	Transport Canada recall 2024760[2] Issued for the model year · Brakes
19 Nov 2026	Listed for sale, Orleans, ON[5] Performance Mazda · asking $8,980
27 Nov 2026	Listing last updated[5] asking $8,980

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 13 live listings, as of 27 Nov 2026

[5] Live public dealer listings on Cardog, as of 27 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.