

Register entry, as of 27 October 2026

Listed for sale

Record ID 5a738a0c9fbd

# 2020 Kia Sedona LX/EX

3.3 L, 6 cylinders · 4x2 · Minivan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**KND MB5C1 1 L 6 607443**

WMI 1-3

Kia Corporation

DESCRIPTOR 4-8

Sedona · 3.3 L

CHECK 9

Computes

YEAR 10

2020

PLANT 11

Sohari

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |         |        |                     |
|------------|---------|--------|---------------------|
| Model year | 2020    | Engine | 3.3 L, 6 cylinders  |
| Make       | Kia     | Fuel   | Gasoline            |
| Model      | Sedona  | Drive  | 4x2                 |
| Trim       | LX/EX   | Maker  | KIA CORPORATION     |
| Body       | Minivan | Plant  | Sohari, South Korea |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/kia/sedona/2020](https://cardog.app/tools/recalls/kia/sedona/2020)

## 3 recalls listed by Transport Canada for this model year

**Label** 2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

**Electrical** 2021680 5 Nov 2021

Issue: Certain vehicles may be equipped with an accessory trailer wiring harness that could fail. Over time, water could leak into the control module and cause a short circuit. If this happens, there could be loss of the trailer lights. Note: This recall affects trailer wiring harness kits that may have been ordered at the time of a vehicle purchase, or purchased separately from a dealer as an aftermarket accessory. Safety Risk: A loss of trailer lights could make the trailer less visible. In addition, other drivers may not recognize that the vehicle ahead is braking or intends to turn. This could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the trailer wiring harness. If the harness is from the lot (batch) affected by this problem, the dealer will replace it. Kia recommends that you should always check to ensure that trailer lights work properly before towing.

**Electrical** 2020318 14 Jul 2020

Issue: On certain vehicles, the nut that attaches the battery cable to the alternator may be loose. This can result in electrical arcing (sparks). Safety Risk: Electrical arcing could increase the risk of a fire. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to inspect, and if necessary, tighten the alternator battery (B+) terminal nut.



Listed for the model year, not checked against your VIN. Kia confirms which apply.  
Check your VIN with Kia Canada or call a Kia dealer with your VIN.  
[www.kia.ca/en/owners/recalls](http://www.kia.ca/en/owners/recalls)

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

### §3 VALUE [4]

This car asks \$21,995<sup>[5]</sup>, \$2,998 over the median of \$18,997<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$6,295             |
| Middle half | \$16,620 – \$20,516 |
| Median ask  | \$18,997            |
| This car    | \$21,995            |

Same configuration · 22 live listings · as of 27 Oct 2026

#### OTHER 2020 KIA SEDONA LISTINGS [5]

|                                |          |
|--------------------------------|----------|
| Québec, QC · 130,087 km        | \$20,689 |
| Victoriaville, QC · 0 km       | \$16,495 |
| Victoriaville, QC · 147,846 km | \$16,495 |
| Victoriaville, QC · 147,846 km | \$16,495 |
| Clareville, NL · 110,835 km    | \$19,995 |
| St. John's, NL · 110,835 km    | \$19,995 |

### §4 EVENTS

|             |                                                                                          |
|-------------|------------------------------------------------------------------------------------------|
| 2020        | Model year 2020 <sup>[1]</sup><br>Assembly plant Sohari, South Korea                     |
| 14 Jul 2020 | Transport Canada recall 2020318 <sup>[2]</sup><br>Issued for the model year · Electrical |
| 5 Nov 2021  | Transport Canada recall 2021680 <sup>[2]</sup><br>Issued for the model year · Electrical |
| 15 Aug 2024 | Transport Canada recall 2024549 <sup>[2]</sup><br>Issued for the model year · Label      |
| 26 Oct 2026 | Listed for sale, Gatineau, QC <sup>[5]</sup><br>Aylmer Kia · asking \$21,995             |

### §5 DOCUMENTS

Window sticker      We have not collected this label yet.



---

**SOURCES**

- |                                                                     |                                                                                  |
|---------------------------------------------------------------------|----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 22 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     |                                                                                  |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026                     |

---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

