Register entry, as of 27 October 2026 Listed for sale Record ID 5e5ff13be69b

# 2017 Kia Sedona LX

3.3 L, 6 cylinders · 4x2 · Minivan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| KND | MB5C1 | 2 | H | 6 | 258199 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Kia Corporation | Sedona · 3.3 L | Computes | 2017 | Sohari | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2017 | Engine | 3.3 L, 6 cylinders |
| Make | Kia | Fuel | Gasoline |
| Model | Sedona | Drive | 4x2 |
| Trim | LX | Maker | KIA CORPORATION |
| Body | Minivan | Plant | Sohari, South Korea |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/sedona/2017

**6** recalls listed by Transport Canada for this model year

### Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

### Airbag

2022023 27 Jan 2022

Issue: On certain vehicles, a defect in the airbag control unit could cause the airbag warning light to turn on. If this happens, the airbag system may not work properly, and the airbags may not inflate in a crash. Safety Risk: An airbag system that does not work properly could create an increased risk of injury in a crash. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to update the airbag control unit software. If the airbag warning light is on because of diagnostic trouble code B1620, the dealer will replace the airbag control unit.

### Electrical

2021680 5 Nov 2021

Issue: Certain vehicles may be equipped with an accessory trailer wiring harness that could fail. Over time, water could leak into the control module and cause a short circuit. If this happens, there could be loss of the trailer lights. Note: This recall affects trailer wiring harness kits that may have been ordered at the time of a vehicle purchase, or purchased separately from a dealer as an aftermarket accessory. Safety Risk: A loss of trailer lights could make the trailer less visible. In addition, other drivers may not recognize that the vehicle ahead is braking or intends to turn. This could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the trailer wiring harness. If the harness is from the lot (batch) affected by this problem, the dealer will replace it. Kia recommends that you should always check to ensure that trailer lights work properly before towing.

### Lights and instruments

2021574 17 Sep 2021

Issue: On certain vehicles, an intermittent problem could cause the turn signals to activate in the opposite direction from what a driver intends. For example, when the driver uses the right turn signal, the left signal could turn on. Safety Risk: Turn signals that do not work properly may cause confusion and could increase the risk of a crash. Corrective Action: Kia will notify owners by mail and instruct you to bring your vehicle to a dealer to update the Smart Junction Box software.

### Seats and restraints

2019103 1 Mar 2019

Issue: On certain vehicles, the wiring for the Occupant Detection System (ODS) could break. This would cause the airbag system to not turn off the airbag when an infant or child is seated in the front passenger seat. This problem only affects vehicles with a manual front-passenger seat. Safety Risk: In a crash, an airbag that deploys in front of an infant or child increases the risk of injury. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to remove a wiring harness clip. This will prevent the wire from breaking. If the wiring is found damaged, the dealer will replace the front passenger seat cushion. Note: If the wiring breaks, the SRS airbag warning light will come on and the "Passenger Airbag Off" indicator will not turn on.

### Structure

2018290 1 Jun 2018

On certain vehicles, the power sliding door control module may not be calibrated correctly. As a result, a closing door may not stop and reverse direction if blocked by an object, increasing the risk of injury to vehicle occupants. Correction: Dealers will reprogram the power sliding door control module software.

> Listed for the model year, not checked against your VIN. Kia confirms which apply.
> Check your VIN with Kia Canada or call a Kia dealer with your VIN.
> www.kia.ca/en/owners/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $11,500[5], $1,474 under the median of $12,974[4].




| | |
|---|---|
| Lowest ask | $9,495 |
| Middle half | $12,119 – $14,133 |
| Median ask | $12,974 |
| This car | $11,500 |

Same configuration · 10 live listings · as of 27 Oct 2026

#### OTHER 2017 KIA SEDONA LISTINGS [5]

| | |
|---|---|
| Kamloops, BC · 154,875 km | $15,298 |
| London, ON · 165,368 km | $11,012 |
| Gloucester, ON · 231,540 km | $8,890 |
| Georgetown, ON · 165,368 km | $11,012 |
| London, ON · 165,368 km | $11,012 |
| Longueuil, QC · 133,400 km | $12,490 |

## §4 EVENTS

2017 Model year 2017[1]
Assembly plant Sohari, South Korea

| | |
|---|---|
| 1 Jun 2018 | Transport Canada recall 2018290[2]<br>Issued for the model year · Structure |
| 1 Mar 2019 | Transport Canada recall 2019103[2]<br>Issued for the model year · Seats and restraints |
| 17 Sep 2021 | Transport Canada recall 2021574[2]<br>Issued for the model year · Lights and instruments |
| 5 Nov 2021 | Transport Canada recall 2021680[2]<br>Issued for the model year · Electrical |
| 27 Jan 2022 | Transport Canada recall 2022023[2]<br>Issued for the model year · Airbag |
| 15 Aug 2024 | Transport Canada recall 2024549[2]<br>Issued for the model year · Label |
| 16 May 2026 | Listed for sale, Calgary, AB[5]<br>Canbridge Motors · asking $11,500 |
| 26 Oct 2026 | Listing last updated[5]<br>asking $11,500 |

## §5 DOCUMENTS

Window sticker — We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 10 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.