Register entry, as of 28 October 2026 Listed for sale Record ID 8eaddb217ff3

2022 Kia Carnival LX, LX Seat Package

3.5 L, 6 cylinders · 4x2 · Minivan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KND	NB5H3	9	N	6	125675
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Kia Corporation	Carnival · 3.5 L	Computes	2022	Sohari	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	3.5 L, 6 cylinders
Make	Kia	Fuel	Gasoline
Model	Carnival	Drive	4x2
Trim	LX, LX Seat Package	Maker	KIA CORPORATION
Body	Minivan	Plant	Sohari, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/carnival/2022

6 recalls listed by Transport Canada for this model year

Fuel system — 2026186 — 10 Apr 2026

Issue: On certain vehicles, the nuts for the crossover fuel pipe may not have been properly tightened. As a result, fuel could leak. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect and tighten the nuts or replace the high-pressure crossover fuel pipe, as necessary.

Label — 2024549 — 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

Structure — 2024023 — 19 Jan 2024

Issue: On certain vehicles, the roof trim may not be properly attached. As a result, the roof trim could loosen and separate from the vehicle. Safety Risk: Roof trim that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, secure or replace the roof trim.

Structure — 2023182 — 29 Mar 2023

Issue: In certain situations, the power sliding door may not stop and reverse if it is blocked. Safety Risk: A power sliding door that doesn't stop when it is blocked could pinch a person and create a risk of injury. Corrective Actions: Kia will notify owners by mail and instruct you to bring your vehicle to a dealership to update the power sliding door control module software. The update will add two (2) warning chimes when the power sliding door begins to open or close, and change the door speed to move more slowly before the door latches.

Electrical

2023149 17 Mar 2023

Issue: Certain vehicles may be equipped with a 4-pin accessory trailer wiring harness kit that could fail. Over time, this could result in a short circuit that can cause the control module to overheat. Note: This recall only affects Kia Genuine 4-pin tow hitch wiring harness kits with the part number R0F67AC200. These kits may have been ordered at the time of a vehicle purchase or purchased separately from a dealer as an aftermarket accessory. Safety Risk: A short circuit can create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Kia will notify owners by mail and instruct you to bring your vehicle to a dealership to inspect the vehicle for a trailer wiring harness kit. If necessary, the dealer will install a 15A fuse and a wire extension kit. Kia advises that if your vehicle has a tow hitch harness installed, you should park it outdoors, and away from other vehicles or structures until the recall repairs have been completed.

Structure

2021712 19 Nov 2021

Issue: On certain vehicles, the passenger-side power sliding door may not latch properly. If this happens, the door could open while driving. Note: If the sliding door does not latch properly, you may see warnings on the instrument cluster and hear an alert chime. If you ignore these warnings and drive above 10 km/h, a continuous door-ajar ringing will sound and the door-ajar warning will show a flashing red symbol. Safety Risk: A door that opens while driving could create a risk of injury. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to repair the door latch on the passenger-side power sliding door.

Listed for the model year, not checked against your VIN. Kia confirms which apply.
Check your VIN with Kia Canada or call a Kia dealer with your VIN.
www.kia.ca/en/owners/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $26,495[5], $2,653 under the median of $29,148[4].

Lowest ask	$15,995
Middle half	$25,150 – $29,994
Median ask	$29,148
This car	$26,495

Same configuration · 26 live listings · as of 28 Oct 2026

OTHER 2022 KIA CARNIVAL LISTINGS [5]

Baie-Comeau, QC · 45,073 km	$34,495
Edmonton, AB · 98,828 km	$29,495
Québec, QC · 81,422 km	$28,977
Regina, SK · 126,528 km	$25,899
Orleans, ON · 86,077 km	$29,350
Chilliwack, BC · 63,973 km	$36,768

§4 EVENTS

2022	Model year 2022[1] Assembly plant Sohari, South Korea
19 Nov 2021	Transport Canada recall 2021712[2] Issued for the model year · Structure

17 Mar 2023	Transport Canada recall 2023149[2] Issued for the model year · Electrical
29 Mar 2023	Transport Canada recall 2023182[2] Issued for the model year · Structure
19 Jan 2024	Transport Canada recall 2024023[2] Issued for the model year · Structure
15 Aug 2024	Transport Canada recall 2024549[2] Issued for the model year · Label
10 Apr 2026	Transport Canada recall 2026186[2] Issued for the model year · Fuel system
26 Oct 2026	Listed for sale, Terrebonne, QC[5] Lallier Auto Inc.(Repentigny) · asking $26,495
27 Oct 2026	Listing last updated[5] asking $26,495

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 26 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.