Register entry, as of 29 October 2026 Listed for sale Record ID 9db0124298dd

2013 Kia Sportage EX/SX

2.0 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KND	PCCA6	5	D	7	423034
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Kia Corporation	Sportage · 2.0 L	Computes	2013	Gwangju	Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	2.0 L, 4 cylinders
Make	Kia	Fuel	Gasoline
Model	Sportage	Drive	4WD
Trim	EX/SX	Maker	KIA CORPORATION
Body	Sport Utility Vehicle	Plant	Gwangju, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/sportage/2013

6 recalls listed by Transport Canada for this model year

Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

Brakes

2023529 26 Sep 2023

Issue: On certain vehicles, the brake hydraulic electronic control unit (HECU) could short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuse(s) for the HECU. Kia recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Engine

2021040 1 Feb 2021

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure could cause a sudden loss of power with an inability to restart. Note: This only affects vehicles equipped with a 2.4 L MPI engine. Safety Risk: A sudden loss of engine power could increase the risk of an accident. An engine failure could also create the risk of a fire. Corrective Actions: Kia will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Kia recommends that you should always follow the correct vehicle maintenance schedule, which is printed in the Owner's Manual. If you experience unusual engine noise, reduced power, or a check engine/oil warning light, Kia advises you to immediately visit a Kia dealership to have your vehicle diagnosed.

Engine

2019153 21 Mar 2019

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure may cause a sudden loss of power with an inability to restart. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Vehicles repaired under Service Campaign SC025 already have this software update.

Fuel system

2018742 28 Dec 2018

On certain vehicles, when repairs were completed under recall campaign 2017-199 (Kia RC109), the high pressure fuel pipe may not have been properly installed on the fuel pump outlet. A fuel leak could occur if the pipe was damaged, misaligned or improperly torqued during the recall repair. A fuel leak, in the presence of an ignition source, could create the risk of a fire causing injury and/or damage to property. Correction: Dealers will inspect the connections of the high pressure fuel pipe to the fuel pump outlet for leaking fuel. If leaking fuel is detected, the fuel pipe will be replaced with a new one.

Engine

2017199 7 Apr 2017

On certain vehicles equipped with 2.0L and 2.4L engines, the engine may contain residual metallic debris from factory machining operations. If debris is present, it could potentially restrict oil flow to the main bearings and rod bearings and could lead to premature wear. If the vehicle continues to be driven with worn bearings, the bearings could fail, which could cause an engine stall while the vehicle is in motion, resulting in loss of motive power which could increase the risk of a crash causing injury and/or property damage. Worn bearings could also result in the illumination of the oil pressure lamp in the instrument cluster. Correction: Dealers will inspect, and if necessary, replace the engine sub-assembly.

> Listed for the model year, not checked against your VIN. Kia confirms which apply.
> Check your VIN with Kia Canada or call a Kia dealer with your VIN.
> www.kia.ca/en/owners/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $11,998[5], $2,050 over the median of $9,948[4].

Lowest ask	$3,999
Middle half	$8,743 – $11,239
Median ask	$9,948
This car	$11,998

Same model year · 12 live listings · as of 29 Oct 2026

OTHER 2013 KIA SPORTAGE LISTINGS [5]

Saskatoon, SK · 198,527 km	$11,995
Sherbrooke, QC · 101,687 km	$10,987
Mount Brydges, ON · 160,000 km	$9,900
Edmonton, AB · 176,223 km	$7,988
Kitchener, ON · 256,639 km	$3,999
Sainte-Rose, QC · 150,373 km	$5,795

§4 EVENTS

2013	Model year 2013[1] Assembly plant Gwangju, South Korea
7 Apr 2017	Transport Canada recall 2017199[2] Issued for the model year · Engine
28 Dec 2018	Transport Canada recall 2018742[2] Issued for the model year · Fuel system
21 Mar 2019	Transport Canada recall 2019153[2] Issued for the model year · Engine
1 Feb 2021	Transport Canada recall 2021040[2] Issued for the model year · Engine
26 Sep 2023	Transport Canada recall 2023529[2] Issued for the model year · Brakes
15 Aug 2024	Transport Canada recall 2024549[2] Issued for the model year · Label
15 May 2026	Listed for sale, Calgary, AB[5] Student Auto Zone · asking $11,998
28 Oct 2026	Listing last updated[5] asking $11,998

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 12 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.