

Register entry, as of 28 October 2026

Listed for sale

Record ID 7064bb033567

2014 Kia Sportage EX

2.0 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KND PCCA6 X E 7 637406

WMI 1-3

Kia Corporation

DESCRIPTOR 4-8

Sportage · 2.0 L

CHECK 9

Computes

YEAR 10

2014

PLANT 11

Gwangju

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	2.0 L, 4 cylinders
Make	Kia	Fuel	Gasoline
Model	Sportage	Drive	4WD
Trim	EX	Maker	KIA CORPORATION
Body	Sport Utility Vehicle	Plant	Gwangju, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/sportage/2014

5 recalls listed by Transport Canada for this model year

Label	2024549 15 Aug 2024
Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.	
Brakes	2022044 2 Feb 2022
Issue: On certain vehicles, the brake hydraulic electronic control unit (HECU) could short circuit. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to replace the ABS multi-fuse. Kia recommends that you should park your vehicle outdoors, and away from other vehicles or structures until the recall repairs have been completed.	
Engine	2019143 18 Mar 2019
Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure may cause a sudden loss of power with an inability to restart. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module. Note: Vehicles repaired under Service Campaign SC023 already have this software update.	



Fuel system

2019098 27 Feb 2019

Issue: When the engine was replaced under warranty or under Kia's Product Improvement Campaign SC023, the high pressure fuel pipe may not have been properly installed on the fuel pump outlet. A fuel leak could occur if the pipe was damaged, misaligned or improperly torqued during the recall repair. Safety Risk: Leaking fuel in the presence of an ignition source could increase the risk of a fire. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer for an inspection. If fuel leakage is detected, the fuel pipe will be replaced with a new one.

Label

2014024 28 Jan 2014

Certain vehicles fail to comply with the requirements of Canada Motor Vehicle Safety Standard 110 – Tire Selection and Rims. The certification label does not contain correct tire pressure information. Note: Correct tire pressure information can be found on the Tire Loading and Information label, directly below the certification label. Correction: Dealers will install a partial label overlay to block out the error, in addition a sticker with the correct tire pressures will be affixed to tire pressure information in the Owner's manual.

Listed for the model year, not checked against your VIN. Kia confirms which apply.
Check your VIN with Kia Canada or call a Kia dealer with your VIN.

www.kia.ca/en/owners/recalls

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$8,990^[5], the median^[4].



Lowest ask	\$3,995
Middle half	\$6,492 – \$10,494
Median ask	\$8,990
This car	\$8,990

Same model year · 3 live listings · as of 28 Oct 2026

OTHER 2014 KIA SPORTAGE LISTINGS [5]

Kentville, NS · 195,022 km	\$3,995
Middleton, NS · 195,022 km	\$3,995
Yarmouth, NS · 195,022 km	\$3,995
Sooke, BC · 122,000 km	\$11,998
Kentville, NS · 195,022 km	\$3,995
New Minas, NS · 195,022 km	\$3,995

§4 EVENTS

2014 Model year 2014^[1]
Assembly plant Gwangju, South Korea

28 Jan 2014 Transport Canada recall 2014024^[2]
Issued for the model year · Label

27 Feb 2019 Transport Canada recall 2019098^[2]
Issued for the model year · Fuel system



18 Mar 2019	Transport Canada recall 2019143 ^[2] Issued for the model year · Engine
2 Feb 2022	Transport Canada recall 2022044 ^[2] Issued for the model year · Brakes
15 Aug 2024	Transport Canada recall 2024549 ^[2] Issued for the model year · Label
25 Oct 2026	Listed for sale, Vaudreuil-Dorion, QC ^[5] Prilo Occasion · asking \$8,990
28 Oct 2026	Listing last updated ^[5] asking \$8,990

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 3 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

