

Register entry, as of 28 October 2026

Listed for sale

Record ID 692baf8ec563

2019 Kia Sportage LX

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KND PMCAC 6 K 7 521358

WMI 1-3

Kia Corporation

DESCRIPTOR 4-8

Sportage · 2.4 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Gwang-Ju

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	2.4 L, 4 cylinders
Make	Kia	Fuel	Gasoline
Model	Sportage	Drive	4WD
Trim	LX	Maker	KIA CORPORATION
Body	Sport Utility Vehicle	Plant	Gwang-Ju, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/sportage/2019

4 recalls listed by Transport Canada for this model year

Label 2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

Electrical 2021680 5 Nov 2021

Issue: Certain vehicles may be equipped with an accessory trailer wiring harness that could fail. Over time, water could leak into the control module and cause a short circuit. If this happens, there could be loss of the trailer lights. Note: This recall affects trailer wiring harness kits that may have been ordered at the time of a vehicle purchase, or purchased separately from a dealer as an aftermarket accessory. Safety Risk: A loss of trailer lights could make the trailer less visible. In addition, other drivers may not recognize that the vehicle ahead is braking or intends to turn. This could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the trailer wiring harness. If the harness is from the lot (batch) affected by this problem, the dealer will replace it. Kia recommends that you should always check to ensure that trailer lights work properly before towing.

Electrical 2021123 8 Mar 2021

Issue: On certain vehicles, a problem in the control module for the antilock brake system (ABS) could cause it to short circuit. Note: This recall does not affect vehicles equipped with Smart Cruise Control (SCC). Safety Risk: A short circuit could create a fire risk. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealer to install new ABS fuse(s) and, on certain models, update the Hydraulic Electronic Control Unit (HECU) software. Kia recommends that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.



Engine

2019639 17 Dec 2019

Issue: Kia Canada is conducting a Product Improvement Campaign that provides an update to the engine control module to detect potential problems before an engine fails. An engine failure may cause a sudden loss of power with an inability to restart. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to update the software for the engine control module.

Listed for the model year, not checked against your VIN. Kia confirms which apply.
Check your VIN with Kia Canada or call a Kia dealer with your VIN.
www.kia.ca/en/owners/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$13,999^[5], \$2,943 under the median of \$16,942^[4].



Lowest ask	\$13,995
Middle half	\$14,968 – \$17,992
Median ask	\$16,942
This car	\$13,999

Same configuration · 12 live listings · as of 28 Oct 2026

OTHER 2019 KIA SPORTAGE LISTINGS ^[5]

Sundridge, ON · 109,211 km	\$15,899
Victoriaville, QC · 97,845 km	\$15,995
Victoriaville, QC · 97,845 km	\$15,995
Kamloops, BC · 116,568 km	\$14,998
Chilliwack, BC · 112,222 km	\$18,999
Victoriaville, QC · 97,845 km	\$15,995

§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Gwang-Ju, South Korea
17 Dec 2019	Transport Canada recall 2019639 ^[2] Issued for the model year · Engine
8 Mar 2021	Transport Canada recall 2021123 ^[2] Issued for the model year · Electrical
5 Nov 2021	Transport Canada recall 2021680 ^[2] Issued for the model year · Electrical
15 Aug 2024	Transport Canada recall 2024549 ^[2] Issued for the model year · Label



2 Jun 2026 Listed for sale, Stettler, AB^[5]
Stettler Dodge Ltd. · asking \$13,999

28 Oct 2026 Listing last updated^[5]
asking \$13,999

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 12 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

