Register entry, as of 29 October 2026 Listed for sale Record ID 5c6702f029bb

2023 Kia Sportage

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

KND	PXCAF	5	P	7	194685
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Kia Corporation	Sportage · 2.5 L	Computes	2023	Gwang-Ju	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	2.5 L, 4 cylinders
Make	Kia	Fuel	Gasoline
Model	Sportage	Drive	4WD
Trim	Not in the decode	Maker	KIA CORPORATION
Body	Sport Utility Vehicle	Plant	Gwang-Ju, South Korea

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/kia/sportage/2023

5 recalls listed by Transport Canada for this model year

Lights and instruments

2025708 19 Dec 2025

Issue: On certain vehicles, the tow hitch harness control module software could cause the instrument cluster to reboot while driving. If this happens, you may not be able to see certain information about the vehicle, including the speedometer, warnings, and tell-tales. Note: This recall only affects vehicles equipped with a 4.2-in screen and a Genuine Kia tow hitch harness. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the tow hitch harness control module.

Label

2024549 15 Aug 2024

Issue: On certain vehicles, the compliance label may be missing information in French. The words listed on the label for "Tires", "Rims", "Front" and "Rear" appear in English only, when they should be listed as "Tires/Pneus", "Rims/Jantes", "Front/Avant" and "Rear/Arriere". Canadian regulations require this information to be listed on the label in both English and French. Safety Risk: These small errors do not affect vehicle safety. Corrective Actions: This is not a recall. Kia has corrected the compliance label for all new vehicles.

Powertrain

2023421 1 Aug 2023

Issue: On certain vehicles, the circuit board in the electric oil pump assembly for the transmission may be damaged. As a result, the circuit board could short circuit and overheat. Safety Risk: A short circuit could create the risk of a fire. Corrective Actions: Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect the transmission electric oil pump assembly, and replace it as necessary. Kia recommends parking your vehicle outside and away from other vehicles or buildings until the recall repairs are completed.

Lights and instruments

2023251 26 Apr 2023

Issue: On certain vehicles, the instrument cluster screen could remain blank when the vehicle is started. If this happens, you may not be able to see certain information about the vehicle, including the odometer, warnings, and malfunction tell-tale graphics. Safety Risk: Warnings and malfunction tell-tale information that doesn't display could increase the risk of a crash. Corrective Actions: Kia will notify owners by mail and instruct you to take your vehicle to a dealership to update the instrument cluster software.

Electrical

2022500 7 Sep 2022

Issue: On certain vehicles, a bracket for the folding rear seats can damage the wiring for the rear seat heater. If this happens, the wiring could short circuit. Note: This recall only affects vehicles equipped with fold-and-dive rear seats with the seat heater option. Safety Risk: A short circuit could create a fire risk, even while the vehicle is parked and turned off. Corrective Action: Kia will notify owners by mail and instruct you to take your vehicle to a dealership to reinforce the rear seat heater wire harness. Kia advises that you may continue to drive your vehicle, but that you should park it outside and away from structures until the recall repairs are completed.

Listed for the model year, not checked against your VIN. Kia confirms which apply.
Check your VIN with Kia Canada or call a Kia dealer with your VIN.
www.kia.ca/en/owners/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $28,989[5], $941 under the median of $29,930[4].

Lowest ask	$23,898
Middle half	$28,120 – $31,114
Median ask	$29,930
This car	$28,989

Same configuration · 74 live listings · as of 29 Oct 2026

OTHER 2023 KIA SPORTAGE LISTINGS [5]

St-Eustache, QC · 9,814 km	$33,500
St-Eustache, QC · 29,594 km	$32,995
Montmagny, QC · 69,266 km	$33,185
Québec, QC · 35,623 km	$25,706
Montmagny, QC · 87,113 km	$22,279
Québec, QC · 47,000 km	$24,589

§4 EVENTS

2023	Model year 2023[1] Assembly plant Gwang-Ju, South Korea
7 Sep 2022	Transport Canada recall 2022500[2] Issued for the model year · Electrical
26 Apr 2023	Transport Canada recall 2023251[2] Issued for the model year · Lights and instruments

1 Aug 2023	Transport Canada recall 2023421[2] Issued for the model year · Powertrain
15 Aug 2024	Transport Canada recall 2024549[2] Issued for the model year · Label
19 Dec 2025	Transport Canada recall 2025708[2] Issued for the model year · Lights and instruments
29 Oct 2026	Listed for sale, Trois-Rivières, QC, QC[5] Mercedes-Benz Trois-Rivières · asking $28,989

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 74 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.