Register entry, as of 29 October 2026 Listed for sale Record ID 902d7f12db8f

2024 Buick Envision Avenir

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

LRB	FZSE4	4	R	D	036477
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Buick · SHANGHAI GENERA…	Envision · 2.0 L	Computes	2024	Dong Yue	Build sequence

§1 IDENTITY [1]

Model year	2024	Engine	2.0 L, 4 cylinders
Make	Buick	Fuel	Gasoline
Model	Envision	Drive	AWD
Trim	Avenir	Maker	SHANGHAI GENERAL MOTORS CORP LTD.
Body	Sport Utility Vehicle	Plant	Dong Yue, China

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/envision/2024

3 recalls listed by Transport Canada for this model year

Lights and instruments

2024678 7 Nov 2024

Issue: On certain vehicles, the brake lamps may flash during certain braking events when the antilock braking system (ABS) is activated. Canadian regulations require the brake lamps to stay on constantly while braking. Safety Risk: Brake lamps that don't work properly could create confusion and cause others not to recognize when a vehicle is braking. This could increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to update the body control module software.

Accessories

2024451 8 Aug 2024

Issue: This recall is for certain all-weather floor liners that were installed before delivery or sold as a dealer accessory. On certain vehicles, the accelerator pedal could get stuck under the floor liner. If this happens, the vehicle may not slow down when you release the accelerator pedal. Safety Risk: A stuck accelerator pedal could cause an unintended acceleration and increase the risk of a crash. Corrective Actions: To reduce the safety risk, General Motors advises you to check for interference with the accelerator pedal and to remove the driver's all-weather floor liner until the recall repairs have been completed. General Motors will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, modify and/or reimburse the driver's all-weather floor liner.

Lights and instruments

2024060 1 Feb 2024

Issue: On certain vehicles, a software problem could cause the lower beam headlamps not to turn on as it becomes dark outside if the multi-function switch is in the "OFF" or "PARKING LAMP" position. This could also cause the daytime running lamps (DRLs) to turn off when the vehicle is moving. As a result, the vehicles may not meet certain requirements of Canadian regulations. Safety Risk: Headlamps and/or DRLs that don't turn on could reduce visibility, make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to update the body control module (BCM)software.

> Listed for the model year, not checked against your VIN. Buick confirms which apply.
> Check your VIN with Buick Canada or call a Buick dealer with your VIN.
> www.buick.ca/en/ownercenter/recalls

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $40,498[5], $1,793 over the median of $38,705[4].

Lowest ask	$33,500
Middle half	$36,995 – $39,724
Median ask	$38,705
This car	$40,498

Same configuration · 37 live listings · as of 29 Oct 2026

OTHER 2024 BUICK ENVISION LISTINGS [5]

Drayton Valley, AB · 38,214 km	$35,995
Moncton, NB · 30,123 km	$33,694
Edmonton, AB · 41,454 km	$35,689
Edmonton, AB · 31,099 km	$38,995
Edmonton, AB · 52,650 km	$35,900
Edmonton, AB · 22,120 km	$39,724

§4 EVENTS

2024	Model year 2024[1] Assembly plant Dong Yue, China
1 Feb 2024	Transport Canada recall 2024060[2] Issued for the model year · Lights and instruments
8 Aug 2024	Transport Canada recall 2024451[2] Issued for the model year · Accessories
7 Nov 2024	Transport Canada recall 2024678[2] Issued for the model year · Lights and instruments
29 Oct 2026	Listed for sale, Prince Albert, SK[5] Mann-Northway Auto Source · asking $40,498

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 37 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.