Register entry, as of 26 October 2026 Listed for sale Record ID ca08b55fd7a1

# 2021 Buick Envision Avenir

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| LRB | FZSR4 | X | M | D | 183762 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Buick · SHANGHAI GENERA… | Envision · 2.0 L | Computes | 2021 | Dong Yue | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2021 | Engine | 2.0 L, 4 cylinders |
| Make | Buick | Fuel | Gasoline |
| Model | Envision | Drive | AWD |
| Trim | Avenir | Maker | SHANGHAI GENERAL MOTORS CORP LTD. |
| Body | Sport Utility Vehicle | Plant | Dong Yue, China |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/envision/2021

**3** recalls listed by Transport Canada for this model year

### Lights and instruments

2024060 1 Feb 2024

Issue: On certain vehicles, a software problem could cause the lower beam headlamps not to turn on as it becomes dark outside if the multi-function switch is in the "OFF" or "PARKING LAMP" position. This could also cause the daytime running lamps (DRLs) to turn off when the vehicle is moving. As a result, the vehicles may not meet certain requirements of Canadian regulations. Safety Risk: Headlamps and/or DRLs that don't turn on could reduce visibility, make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to update the body control module (BCM)software.

### Lights and instruments

2022700 8 Dec 2022

Issue: On certain vehicles, the daytime running lamps (DRLs) may stay on when the headlamps are on. Canadian regulations require the DRLs to turn off when the headlamps are on. Safety Risk: Daytime running lamps that stay on could cause glare for oncoming drivers and increase the risk of a crash. Corrective Action: General Motors will notify owners by mail and instruct you to take your vehicle to a dealership to update the body control module (BCM) software.

### Airbag

2021348 3 Jun 2021

Issue: On certain vehicles, a software problem could cause the airbag warning light not to turn on when there is a fault in the airbag system. As a result, a driver might not be alerted of the problem and the airbags may not work properly in a crash. Safety Risk: An airbag system that does not work properly could create an increased risk of injury in a crash. Corrective Actions: General Motors will notify owners by mail and send a wireless over-the-air software update to each vehicle. Alternatively, you may schedule an appointment to have the update performed by a dealer.

> Listed for the model year, not checked against your VIN. Buick confirms which apply.
> Check your VIN with Buick Canada or call a Buick dealer with your VIN.
> www.buick.ca/en/ownercenter/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $23,999[5], $789 under the median of $24,788[4].

| | |
|---|---|
| Lowest ask | $15,999 |
| Middle half | $23,998 – $27,900 |
| Median ask | $24,788 |
| This car | $23,999 |

Same configuration · 13 live listings · as of 26 Oct 2026

### OTHER 2021 BUICK ENVISION LISTINGS [5]

| | |
|---|---|
| Orangeville, ON · 116,518 km | $22,989 |
| Cold Lake, AB · 136,411 km | $22,998 |
| Kamloops, BC · 86,916 km | $33,995 |
| Salmon Arm, BC · 126,914 km | $24,989 |
| Orangeville, ON · 116,518 km | $22,989 |
| Sherwood Park, AB · 114,160 km | $27,780 |

## §4 EVENTS

| | |
|---|---|
| 2021 | Model year 2021[1]<br>Assembly plant Dong Yue, China |
| 3 Jun 2021 | Transport Canada recall 2021348[2]<br>Issued for the model year · Airbag |
| 8 Dec 2022 | Transport Canada recall 2022700[2]<br>Issued for the model year · Lights and instruments |
| 1 Feb 2024 | Transport Canada recall 2024060[2]<br>Issued for the model year · Lights and instruments |
| 25 Oct 2026 | Listed for sale, Camrose, AB[5]<br>McClellan Wheaton Chevrolet Buick GMC Ltd. · asking $23,999 |
| 26 Oct 2026 | Listing last updated[5]<br>asking $23,999 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 13 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.