Register entry, as of 28 October 2026 Listed for sale Record ID 2b1e0b154703

# 2021 Ford Ecosport

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| MAJ | 6S3GL | 4 | M | C | 430016 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Ford India Ltd | Ecosport · 2.0 L | Computes | 2021 | Chennai | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2021 | Engine | 2.0 L, 4 cylinders |
| Make | Ford | Fuel | Gasoline |
| Model | Ecosport | Drive | AWD |
| Trim | Not in the decode | Maker | Ford India Ltd |
| Body | Sport Utility Vehicle | Plant | Chennai, Tamil Nadu, India |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/ecosport/2021

**3** recalls listed by Transport Canada for this model year

### Visual system

2025360 27 Jun 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the SYNC software.

### Powertrain

2025104 2 Mar 2025

Issue: On certain vehicles, the front axle shafts may not have been installed properly. As a result, the front axle shaft(s) could become damaged and/or separate from the transmission, and cause a sudden loss of power to the wheels. Additionally, if the vehicle is parked and the parking brake isn't applied, the vehicle could roll away. Note: This recall only affects vehicles equipped with a 6-speed automatic transmission. Safety Risk: A loss of power to the wheels could increase the risk of a crash. A parked vehicle that moves suddenly could create a risk of a crash or an injury. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the axle shaft(s).

### Engine

2023704 22 Dec 2023

Issue: On certain vehicles, the engine oil pump tensioner and/or the engine oil pump drive belt could fail and cause a loss of engine oil pressure. If this happens, the engine could fail and cause a loss of power to the wheels and a loss of power braking assist. Note: This recall only affects vehicles equipped with a 1.0L engine. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. A loss of power brakes can cause an increase in brake pedal force and lead to an increase in stopping distance. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the oil pump drive belt tensioner assembly. The dealer will also replace the oil pump drive belt.

> Listed for the model year, not checked against your VIN. Ford confirms which apply.
> Check your VIN with Ford Canada or call a Ford dealer with your VIN.
> www.ford.ca/support/recalls/

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $19,998[5], $2,998 over the median of $17,000[4].

| | |
|---|---|
| Lowest ask | $7,488 |
| Middle half | $16,242 – $17,997 |
| Median ask | $17,000 |
| This car | $19,998 |

Same model year · 19 live listings · as of 28 Oct 2026

### OTHER 2021 FORD ECOSPORT LISTINGS [5]

| | |
|---|---|
| Mississauga, ON · 22,556 km | $19,802 |
| Leamington, ON · 22,556 km | $19,802 |
| Toronto, ON · 22,556 km | $19,802 |
| Carbonear, NL · 79,190 km | $17,995 |
| Clarenville, NL · 79,190 km | $17,995 |
| Windsor, ON · 22,556 km | $19,802 |

## §4 EVENTS

| | |
|---|---|
| 2021 | Model year 2021[1]<br>Assembly plant Chennai, Tamil Nadu, India |
| 22 Dec 2023 | Transport Canada recall 2023704[2]<br>Issued for the model year · Engine |
| 2 Mar 2025 | Transport Canada recall 2025104[2]<br>Issued for the model year · Powertrain |
| 27 Jun 2025 | Transport Canada recall 2025360[2]<br>Issued for the model year · Visual system |
| 15 Sep 2026 | Listed for sale, Victoria, BC[5]<br>SUBURBAN MOTORS · asking $19,998 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $19,998 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 19 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.