Register entry, as of 29 October 2026 Listed for sale Record ID 69373ad29206

2022 Ford Ecosport

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

MAJ	6S3GL	7	N	C	470852
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Ford India Ltd	Ecosport · 2.0 L	Computes	2022	Chennai	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	2.0 L, 4 cylinders
Make	Ford	Fuel	Gasoline
Model	Ecosport	Drive	AWD
Trim	Not in the decode	Maker	Ford India Ltd
Body	Sport Utility Vehicle	Plant	Chennai, Tamil Nadu, India

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/ecosport/2022

2 recalls listed by Transport Canada for this model year

Powertrain

2025104 2 Mar 2025

Issue: On certain vehicles, the front axle shafts may not have been installed properly. As a result, the front axle shaft(s) could become damaged and/or separate from the transmission, and cause a sudden loss of power to the wheels. Additionally, if the vehicle is parked and the parking brake isn't applied, the vehicle could roll away. Note: This recall only affects vehicles equipped with a 6-speed automatic transmission. Safety Risk: A loss of power to the wheels could increase the risk of a crash. A parked vehicle that moves suddenly could create a risk of a crash or an injury. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the axle shaft(s).

Engine

2023704 22 Dec 2023

Issue: On certain vehicles, the engine oil pump tensioner and/or the engine oil pump drive belt could fail and cause a loss of engine oil pressure. If this happens, the engine could fail and cause a loss of power to the wheels and a loss of power braking assist. Note: This recall only affects vehicles equipped with a 1.0L engine. Safety Risk: A sudden loss of power to the wheels could increase the risk of a crash. A loss of power brakes can cause an increase in brake pedal force and lead to an increase in stopping distance. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the oil pump drive belt tensioner assembly. The dealer will also replace the oil pump drive belt.

Listed for the model year, not checked against your VIN. Ford confirms which apply.
Check your VIN with Ford Canada or call a Ford dealer with your VIN.
www.ford.ca/support/recalls/

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $20,695[5], $1,195 over the median of $19,500[4].

Lowest ask	$16,448
Middle half	$17,699 – $19,999
Median ask	$19,500
This car	$20,695

Same configuration · 21 live listings · as of 29 Oct 2026

OTHER 2022 FORD ECOSPORT LISTINGS [5]

Sydney, NS · 67,286 km	$20,995
St. Catharines, ON · 52,523 km	$20,168
Grimsby, ON · 52,523 km	$20,168
Saint-Hyacinthe, QC · 11,267 km	$19,998
Kentville, NS · 30,994 km	$19,999
Windsor, ON · 35,871 km	$20,999

§4 EVENTS

2022	Model year 2022[1] Assembly plant Chennai, Tamil Nadu, India
22 Dec 2023	Transport Canada recall 2023704[2] Issued for the model year · Engine
2 Mar 2025	Transport Canada recall 2025104[2] Issued for the model year · Powertrain
29 Jul 2026	Listed for sale, Bathurst, NB[5] Bayside Hyundai · asking $20,695
28 Oct 2026	Listing last updated[5] asking $20,695

§5 DOCUMENTS

Window sticker — We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 21 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.