Register entry, as of 28 October 2026 Listed for sale Record ID 16a0179e4267

2018 Toyota C-HR XLE/XLE Premium

2.0 L, 4 cylinders · FWD · Crossover Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

NMT	KHMBX	0	J	R	014884
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Toyota Motor Manufacturi…	C-HR · 2.0 L	Computes	2018	Arifiye	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	2.0 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	C-HR	Drive	FWD
Trim	XLE/XLE Premium	Maker	TOYOTA MOTOR MANUFACTURING,TURKEY ,INC.
Body	Crossover Utility Vehicle	Plant	Arifiye, Sakarya, TüRkiye

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/c-hr/2018

3 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Brakes

2017559 15 Nov 2017

Certain vehicles may fail to conform to Canada Motor Vehicle Safety Standard (CMVSS) 135 - Light Vehicle Brake Systems. The electric parking brake (EPB) may not apply or release due to an incorrectly programmed skid control ECU. If this occurs while the vehicle is parked on a grade without being place into the park position and the EPB warnings are ignored, the vehicle may roll away which would increase the risk of injury and/or damage to property. Correction: Dealers will update the programming of the skid control ECU.

Electrical

2017363 20 Jul 2017

On certain vehicles, the electrical power cords of some dealer installed block heaters may have been improperly manufactured, causing the wires to contact each other, resulting in a short circuit. A short circuit could lead to a fire which would increase the risk of injury and/or damage to property. Correction: For vehicles where the subject block heater was approved for installation, the dealer will replace the block heater assembly with a new one of an improved design. For vehicles where the subject block heater was not approved for installation, dealers will remove the block heater assembly. In the interim, until the remedy can be performed, dealers will cut the plug end from the block heater cord to disable the block heater's operation.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
www.toyota.ca/en/owners/recalls/

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $16,999[5], $1,805 under the median of $18,804[4].



Lowest ask	$15,295
Middle half	$16,997 – $19,996
Median ask	$18,804
This car	$16,999

Same configuration · 28 live listings · as of 28 Oct 2026

OTHER 2018 TOYOTA C-HR LISTINGS [5]

Calgary, AB · 167,601 km	$15,900
Stouffville, ON · 119,018 km	$21,500
London, ON · 201,235 km	$3,100
Saskatoon, SK · 111,855 km	$20,583
Welland, ON · 151,885 km	$17,678
Victoria, BC · 43,438 km	$19,930

§4 EVENTS

2018	Model year 2018[1] Assembly plant Arifiye, Sakarya, TüRkiye
20 Jul 2017	Transport Canada recall 2017363[2] Issued for the model year · Electrical
15 Nov 2017	Transport Canada recall 2017559[2] Issued for the model year · Brakes
24 Nov 2021	Transport Canada recall 2021723[2] Issued for the model year · Electrical
24 Oct 2026	Listed for sale, St. Catharines, ON[5] Performance Toyota · asking $16,999

28 Oct 2026	Listing last updated[5] asking $16,999

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 28 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.