Register entry, as of 27 October 2026 Listed for sale Record ID 9b86e26fd09e

# 2018 Jaguar F-PACE R Sport

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

| SAD | CL2FN | 4 | J | A | 297423 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Jaguar Land Rover Limited | F-PACE · 2.0 L | Computes | 2018 | Solihull | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2018 | Engine | 2.0 L, 4 cylinders |
| Make | Jaguar | Fuel | Diesel |
| Model | F-PACE | Drive | AWD |
| Trim | R Sport | Maker | JAGUAR LAND ROVER LIMITED |
| Body | Sport Utility Vehicle | Plant | Solihull, United Kingdom |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/jaguar/f-pace/2018

**5** recalls listed by Transport Canada for this model year

### Lights and instruments — 2021101 — 26 Feb 2021

Issue: On certain vehicles, when the Automatic High Beam (AHB) system is turned on, the AHB tell-tale indicator on the instrument panel may not turn on. This could lead you to drive without knowing that high beam lights can turn on automatically. Canadian regulations require a tell-tale indicator to turn on when the automatic high beams are activated. Safety Risk: A driver that does not know that the high beam lights are turned on could create glare for other drivers and increase the risk of a crash. Corrective Actions: Jaguar will notify owners by mail and instruct you to take your vehicle to a dealer to update vehicle software.

### Fuel system — 2018066 — 1 Feb 2018

On certain vehicles, the brazing fuel rail end caps may not seal properly which could cause a fuel leak over time. A Fuel leak in the presence of an ignition source could result in a fire causing injury and/or damage to property. Correction: Dealers will replace the fuel rail.

### Lights and instruments — 2018029 — 15 Jan 2018

On certain vehicles, the instrument cluster could go blank intermittently and be unable to display important information. This could result in the driver not being aware of vehicle speed or any malfunction lights turning on, which could affect vehicle performance and increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will update the vehicle software. Note: This recall is an expansion of recall 2017-524.

### Lights and instruments — 2017524 — 26 Oct 2017

On certain vehicles, the instrument cluster could go blank intermittently and be unable to display important information. This could result in the driver not being aware of vehicle speed or any malfunction lights turning on, which could affect vehicle performance and increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will update the vehicle software.

### Fuel system

2017234 27 Apr 2017

On certain vehicles equipped with a 2.0L diesel engine, the fuel return hose could leak. This could cause a the fuel to leak onto the road surface which can present a skid hazard to other road users increasing the risk of a crash causing injury and/or damage to property. A fuel leak in the presence of an ignition source could also cause a fire. Correction: Dealers will replace the fuel return hose.

Listed for the model year, not checked against your VIN. Jaguar confirms which apply.
Check your VIN with Jaguar Canada or call a Jaguar dealer with your VIN.
www.jaguar.com/en-ca/jdx/ownership/vin-recall.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $14,995[5], $3,997 under the median of $18,992[4].

| | |
|---|---|
| Lowest ask | $12,900 |
| Middle half | $15,942 – $22,544 |
| Median ask | $18,992 |
| This car | $14,995 |

Same model year · 27 live listings · as of 27 Oct 2026

OTHER 2018 JAGUAR F-PACE LISTINGS [5]

| | |
|---|---|
| Georgetown, ON · 119,938 km | $22,089 |
| London, ON · 119,938 km | $22,089 |
| Kamloops, BC · 91,056 km | $23,998 |
| Courtenay, BC · 120,794 km | $19,995 |
| London, ON · 119,938 km | $22,089 |
| St. Catharines, ON · 138,969 km | $19,995 |

## §4 EVENTS

| | |
|---|---|
| 2018 | Model year 2018[1]<br>Assembly plant Solihull, United Kingdom |
| 27 Apr 2017 | Transport Canada recall 2017234[2]<br>Issued for the model year · Fuel system |
| 26 Oct 2017 | Transport Canada recall 2017524[2]<br>Issued for the model year · Lights and instruments |
| 15 Jan 2018 | Transport Canada recall 2018029[2]<br>Issued for the model year · Lights and instruments |
| 1 Feb 2018 | Transport Canada recall 2018066[2]<br>Issued for the model year · Fuel system |
| 26 Feb 2021 | Transport Canada recall 2021101[2]<br>Issued for the model year · Lights and instruments |

| | |
|---|---|
| 19 Jan 2026 | Listed for sale, Toronto, ON[5]<br>Ryder Auto Sales · asking $14,995 |
| 24 Oct 2026 | Listing last updated[5]<br>asking $14,995 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 27 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.