

Register entry, as of 27 October 2026

Listed for sale

Record ID 6ded99a44037

# 2019 Jaguar F-PACE R Sport

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**SAD CL2FX 4 K A 614779**

WMI 1-3

Jaguar Land Rover Limited

DESCRIPTOR 4-8

F-PACE · 2.0 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Solihull

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                       |        |                           |
|------------|-----------------------|--------|---------------------------|
| Model year | 2019                  | Engine | 2.0 L, 4 cylinders        |
| Make       | Jaguar                | Fuel   | Gasoline                  |
| Model      | F-PACE                | Drive  | AWD                       |
| Trim       | R Sport               | Maker  | JAGUAR LAND ROVER LIMITED |
| Body       | Sport Utility Vehicle | Plant  | Solihull, United Kingdom  |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/jaguar/f-pace/2019](https://cardog.app/tools/recalls/jaguar/f-pace/2019)

## 2 recalls listed by Transport Canada for this model year

### Lights and instruments

2021101 26 Feb 2021

Issue: On certain vehicles, when the Automatic High Beam (AHB) system is turned on, the AHB tell-tale indicator on the instrument panel may not turn on. This could lead you to drive without knowing that high beam lights can turn on automatically. Canadian regulations require a tell-tale indicator to turn on when the automatic high beams are activated. Safety Risk: A driver that does not know that the high beam lights are turned on could create glare for other drivers and increase the risk of a crash. Corrective Actions: Jaguar will notify owners by mail and instruct you to take your vehicle to a dealer to update vehicle software.

### Engine

2019028 17 Jan 2019

Issue: On certain vehicles, the engine crankshaft pulley bolt may have been manufactured improperly. This could cause it to crack and fail. If this happens, the crankshaft could break and cause a sudden engine failure. A driver may hear loud noises and see warning lights on the dash immediately before the engine fails. Safety Risk: An engine failure could increase the risk of a crash. Additionally, a loose pulley could separate from the engine and cause damage. If it separates from the vehicle, it could become a hazard for bystanders or other drivers. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to an authorized repair facility to have the crankshaft pulley bolt replaced with a new one.

Listed for the model year, not checked against your VIN. Jaguar confirms which apply.

Check your VIN with Jaguar Canada or call a Jaguar dealer with your VIN.


[www.jaguar.com/en-ca/jdx/ownership/vin-recall.html](https://www.jaguar.com/en-ca/jdx/ownership/vin-recall.html)

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>



## §3 VALUE [4]

This car asks \$24,975<sup>[5]</sup>, \$5,298 over the median of \$19,677<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$14,888            |
| Middle half | \$17,954 – \$23,995 |
| Median ask  | \$19,677            |
| This car    | \$24,975            |

Same model year · 22 live listings · as of 27 Oct 2026

## OTHER 2019 JAGUAR F-PACE LISTINGS [5]

|                             |          |
|-----------------------------|----------|
| Quebec, QC · 69,000 km      | \$23,995 |
| Montréal, QC · 127,000 km   | \$14,995 |
| Ancaster, ON · 69,000 km    | \$23,995 |
| Abbotsford, BC · 92,550 km  | \$26,999 |
| Toronto, ON · 0 km          | \$18,888 |
| North York, ON · 108,943 km | \$19,880 |

## §4 EVENTS

|             |                                                                                                      |
|-------------|------------------------------------------------------------------------------------------------------|
| 2019        | Model year 2019 <sup>[1]</sup><br>Assembly plant Solihull, United Kingdom                            |
| 17 Jan 2019 | Transport Canada recall 2019028 <sup>[2]</sup><br>Issued for the model year · Engine                 |
| 26 Feb 2021 | Transport Canada recall 2021101 <sup>[2]</sup><br>Issued for the model year · Lights and instruments |
| 4 Feb 2026  | Listed for sale, Saint-Eustache, QC <sup>[5]</sup><br>Autozoom · asking \$24,975                     |
| 27 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$24,975                                               |

## §5 DOCUMENTS

|                |                                                          |
|----------------|----------------------------------------------------------|
| Window sticker | We do not collect window stickers for this manufacturer. |
|----------------|----------------------------------------------------------|

## SOURCES

|                                                                     |                                                                               |
|---------------------------------------------------------------------|-------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 22 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 27 Oct 2026                  |
| [3] NHTSA recall records (United States), listed for the model year |                                                                               |



---

**STATEMENT OF SCOPE**

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

