Register entry, as of 26 October 2026 Listed for sale Record ID 9d59ae542166

# 2017 Jaguar F-TYPE SVR

5.0 L, 8 cylinders · AWD · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| SAJ | XJ6J8 | 2 | H | M | K46072 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Jaguar Land Rover Limited | F-TYPE · 5.0 L | Computes | 2017 | United Kingdom | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2017 | Engine | 5.0 L, 8 cylinders |
| Make | Jaguar | Fuel | Gasoline |
| Model | F-TYPE | Drive | AWD |
| Trim | SVR | Maker | JAGUAR LAND ROVER LIMITED |
| Body | Coupe | Plant | United Kingdom |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/jaguar/f-type/2017

**2** recalls listed by Transport Canada for this model year

### Seats and restraints

2016651 22 Dec 2016

Certain vehicles may have been equipped with front seat belt pretensioners that do not meet specifications. This could cause the pretensioners to fail to deploy in the event of a crash, which could increase the risk of injury to the front seat occupants. Correction: Dealers will check the production date of the front seat belt assemblies (which incorporate the pretensioners) and replace as necessary.

### Suspension

2016531 27 Oct 2016

On certain F-TYPE SVR specification vehicles, the rear lower control arm knuckle assembly deformable bolt may have been torqued multiple times during the time of assembly contrary to the specification. This could cause the anti-corrosion coating to come off, exposing bare metal to the environment, resulting in premature fatigue failure causing separation of the joint. A separating control arm knuckle assembly could affect vehicle handling and stability increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect and replace any over torqued deformable bolt.

Listed for the model year, not checked against your VIN. Jaguar confirms which apply.
Check your VIN with Jaguar Canada or call a Jaguar dealer with your VIN.
www.jaguar.com/en-ca/jdx/ownership/vin-recall.html

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $109,777[5], $53,782 over the median of $55,995[4].

| | |
|---|---|
| Lowest ask | $41,900 |
| Middle half | $46,995 – $91,995 |
| Median ask | $55,995 |
| This car | $109,777 |

Same model year · 9 live listings · as of 26 Oct 2026

### OTHER 2017 JAGUAR F-TYPE LISTINGS [5]

| | |
|---|---|
| Scarborough, ON · 96,916 km | $45,988 |
| Québec, QC · 48,721 km | $42,850 |
| Scarborough, ON · 0 km | $52,777 |
| Scarborough, ON · 0 km | $57,777 |
| North Vancouver, BC · 39,930 km | $91,995 |
| Vancouver, BC · 39,930 km | $91,995 |

## §4 EVENTS

| | |
|---|---|
| 2017 | Model year 2017[1]<br>Assembly plant United Kingdom |
| 27 Oct 2016 | Transport Canada recall 2016531[2]<br>Issued for the model year · Suspension |
| 22 Dec 2016 | Transport Canada recall 2016651[2]<br>Issued for the model year · Seats and restraints |
| 24 Oct 2026 | Listed for sale, Scarborough, ON[5]<br>Manhattan Motorcars · asking $109,777 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 9 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.