Register entry, as of 29 October 2026 Listed for sale Record ID 7c85ac33042c

2023 Land Rover Range Rover Sport P400 Dynamic SE

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

SAL	1L9FU	X	P	A	106480
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jaguar Land Rover Limited	Range Rover Sport · 3.0 L	Computes	2023	Solihull	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	3.0 L, 6 cylinders
Make	Land Rover	Fuel	Gasoline
Model	Range Rover Sport	Drive	AWD
Trim	P400 Dynamic SE	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Solihull, United Kingdom

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/range-rover-sport/2023

8 recalls listed by Transport Canada for this model year

High voltage

2026442 17 Sep 2026

Issue: On certain vehicles, the DC/DC converter could fail. As a result, the 12 V battery would not charge and a red "Stop Safely Electrical Fault Detected" warning message would be displayed. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels and/or the vehicle's lights could turn off. Note: This recall is an expansion of Transport Canada recall no. 2026-196. Vehicles repaired under that recall don't require this repair. This recall only affects certain mild hybrid electric vehicles (MHEV). Safety Risk: A loss of power to the wheels could increase the risk of a crash. Exterior lights that don't work may make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle load balancing software.

High voltage

2026196 17 Apr 2026

Issue: On certain vehicles, the DC/DC converter could fail. As a result, the 12 V battery would not charge and a red "Stop Safely Electrical Fault Detected" warning message would be displayed. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels and/or the vehicle's lights could turn off. Note: This recall only affects certain mild hybrid electric vehicles (MHEV). Safety Risk: A loss of power to the wheels could increase the risk of a crash. Exterior lights that don't work may make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail. The corrective actions for this recall are under development.

Structure

2026074 19 Feb 2026

Issue: On certain vehicles, the side trim(s) on the panoramic sunroof may not be properly attached. As a result, the trim(s) could loosen and separate from the vehicle. Safety Risk: Trim that detaches from the vehicle could create a hazard for others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to secure the panoramic roof side trims.

Engine

2024599 10 Oct 2024

Issue: This recall is for certain replacement engines. The oil filter housing may not have been manufactured properly. Over time, the housing could crack and cause oil to leak onto hot components in the engine compartment. Safety Risk: Oil that leaks onto hot components can create the risk of a fire. Additionally, an oil leak could create a hazard for others and increase the risk of a crash. Corrective Actions: None of the affected engines have been installed in vehicles. Land Rover will instruct dealers to replace the oil filter housing assembly before each engine is installed.

Lights and instruments

2023687 21 Dec 2023

Issue: On certain vehicles, water could leak into the right-rear tail lamps. As a result, the side marker lamps, brake lamps, reverse lamps and turn signals may not work. Safety Risk: Brake lamps, reverse lamps and/or turn signals that don't work could cause a person not to recognize that a vehicle ahead is braking, backing up or about to turn. Side marker lamps that don't work could make the vehicle less visible to others. All these issues could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to replace the right-rear tail lamps.

Accessories

2023269 4 May 2023

Issue: On certain vehicles, the latch for the storage compartment in the second-row armrest could fail. If this happens, the storage compartment lid could open in a crash. Safety Risk: A storage compartment that opens in a crash could allow objects to move inside this vehicle, and increase the risk of an injury. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to replace the latch on second-row armrest storage compartment.

2 more on the model-year record, cardog.app/tools/recalls/land-rover/range-rover-sport/2023

> Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
> Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
> www.landrover.ca/en/ownership/vin-recall.html

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $84,599[5], $601 over the median of $83,998[4].

Lowest ask	$76,898
Middle half	$79,839 – $85,424
Median ask	$83,998
This car	$84,599

Same configuration · 8 live listings · as of 29 Oct 2026

OTHER 2023 LAND ROVER RANGE ROVER SPORT LISTINGS [5]

Ajax, ON · 37,133 km	$76,987
Ottawa, ON · 47,888 km	$77,995
Mississauga, ON · 55,683 km	$81,899
Leamington, ON · 55,683 km	$81,899
Essex, ON · 55,683 km	$81,899
Chilliwack, BC · 43,416 km	$78,995

§4 EVENTS

2023	Model year 2023[1] Assembly plant Solihull, United Kingdom
21 Jul 2022	Transport Canada recall 2022392[2] Issued for the model year · Seats and restraints
2 Feb 2023	Transport Canada recall 2023039[2] Issued for the model year · Engine
4 May 2023	Transport Canada recall 2023269[2] Issued for the model year · Accessories
21 Dec 2023	Transport Canada recall 2023687[2] Issued for the model year · Lights and instruments
10 Oct 2024	Transport Canada recall 2024599[2] Issued for the model year · Engine
19 Feb 2026	Transport Canada recall 2026074[2] Issued for the model year · Structure
16 Mar 2026	Listed for sale, Waterloo, ON[5] Jaguar Land Rover Waterloo · asking $84,599
17 Apr 2026	Transport Canada recall 2026196[2] Issued for the model year · High voltage
17 Sep 2026	Transport Canada recall 2026442[2] Issued for the model year · High voltage
28 Oct 2026	Listing last updated[5] asking $84,599

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 8 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.