Register entry, as of 23 November 2026 Listed for sale Record ID 2b9a19698548

2023 Land Rover Discovery Sport HSE R-Dynamic

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

SAL	CM2FX	0	P	H	333319
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jaguar Land Rover Limited	Discovery Sport · 2.0 L	Computes	2023	Halewood	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	2.0 L, 4 cylinders
Make	Land Rover	Fuel	Gasoline
Model	Discovery Sport	Drive	AWD
Trim	HSE R-Dynamic	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Halewood, United Kingdom

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/discovery-sport/2023

3 recalls listed by Transport Canada for this model year

High voltage

2026442 17 Sep 2026

Issue: On certain vehicles, the DC/DC converter could fail. As a result, the 12 V battery would not charge and a red "Stop Safely Electrical Fault Detected" warning message would be displayed. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels and/or the vehicle's lights could turn off. Note: This recall is an expansion of Transport Canada recall no. 2026-196. Vehicles repaired under that recall don't require this repair. This recall only affects certain mild hybrid electric vehicles (MHEV). Safety Risk: A loss of power to the wheels could increase the risk of a crash. Exterior lights that don't work may make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle load balancing software.

Visual system

2025015 16 Jan 2025

Issue: On certain vehicles, a software problem could cause the touch screen to remain blank when the vehicle is started. As a result, the rearview camera image would not appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Note: This recall only affects vehicles equipped with a 10-inch touch screen. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to update the touch screen software.

Seats and restraints

2022392 21 Jul 2022

Issue: On certain vehicles, the driver and front passenger seat belt pretensioners could be damaged. As a result, the seat belt pretensioners may not work properly in a crash. Safety Risk: A seat belt pretensioner that does not work properly could increase the risk of injury in a crash. Corrective Actions: Land Rover will contact owners by mail and instruct you to bring your vehicle to a dealership to inspect the front seat belt pretensioner tubes for damage. The dealer will replace the driver and front passenger seat belt retractors, if necessary.

> Listed for the model year, not checked against your VIN. Land Rover confirms which apply. Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
> www.landrover.ca/en/ownership/vin-recall.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $38,990[5], $7,495 over the median of $31,495[4].



Lowest ask	$26,790
Middle half	$28,994 – $34,290
Median ask	$31,495
This car	$38,990

Same model year · 19 live listings · as of 22 Nov 2026

OTHER 2023 LAND ROVER DISCOVERY SPORT LISTINGS [5]

Edmonton, AB · 50,141 km	$32,000
Oakville, ON · 99,433 km	$26,790
Vaudreuil-Dorion, QC · 105,202 km	$27,998
Truro, NS · 75,920 km	$28,991
Brampton, ON · 76,648 km	$29,998
Ajax, ON · 72,850 km	$29,888

§4 EVENTS

2023	Model year 2023[1] Assembly plant Halewood, United Kingdom
21 Jul 2022	Transport Canada recall 2022392[2] Issued for the model year · Seats and restraints
16 Jan 2025	Transport Canada recall 2025015[2] Issued for the model year · Visual system
17 Sep 2026	Transport Canada recall 2026442[2] Issued for the model year · High voltage
18 Nov 2026	Listed for sale, Richmond, BC[5] Land Rover Richmond · asking $38,990

23 Nov 2026	Listing last updated[5] asking $38,990	

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 19 live listings, as of 22 Nov 2026

[5] Live public dealer listings on Cardog, as of 23 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.