

2022 Land Rover Discovery Sport HSE R-Dynamic

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER ^[1]

SAL **CM2FX** **8** **N** **H** **912054**

WMI 1-3

Jaguar Land Rover Limited

DESCRIPTOR 4-8

Discovery Sport · 2.0 L

CHECK 9

Computes

YEAR 10

2022

PLANT 11

Halewood

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2022	Engine	2.0 L, 4 cylinders
Make	Land Rover	Fuel	Gasoline
Model	Discovery Sport	Drive	AWD
Trim	HSE R-Dynamic	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Halewood, United Kingdom

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/land-rover/discovery-sport/2022

2 recalls listed by Transport Canada for this model year

High voltage

2026442 17 Sep 2026

Issue: On certain vehicles, the DC/DC converter could fail. As a result, the 12 V battery would not charge and a red "Stop Safely Electrical Fault Detected" warning message would be displayed. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels and/or the vehicle's lights could turn off. Note: This recall is an expansion of Transport Canada recall no. 2026-196. Vehicles repaired under that recall don't require this repair. This recall only affects certain mild hybrid electric vehicles (MHEV). Safety Risk: A loss of power to the wheels could increase the risk of a crash. Exterior lights that don't work may make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle load balancing software.

Seats and restraints

2022392 21 Jul 2022

Issue: On certain vehicles, the driver and front passenger seat belt pretensioners could be damaged. As a result, the seat belt pretensioners may not work properly in a crash. Safety Risk: A seat belt pretensioner that does not work properly could increase the risk of injury in a crash. Corrective Actions: Land Rover will contact owners by mail and instruct you to bring your vehicle to a dealership to inspect the front seat belt pretensioner tubes for damage. The dealer will replace the driver and front passenger seat belt retractors, if necessary.

Listed for the model year, not checked against your VIN. Land Rover confirms which apply.

Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.

www.landrover.ca/en/ownership/vin-recall.html



United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$23,977^[5], the median^[4].



Lowest ask	\$20,995
Middle half	\$22,486 – \$24,986
Median ask	\$23,977
This car	\$23,977

Same model year · 3 live listings · as of 26 Oct 2026

OTHER 2022 LAND ROVER DISCOVERY SPORT LISTINGS ^[5]

Belleville, ON · 95,265 km	\$25,995
North York, ON · 108,050 km	\$20,995

§4 EVENTS

2022	Model year 2022 ^[1] Assembly plant Halewood, United Kingdom
21 Jul 2022	Transport Canada recall 2022392 ^[2] Issued for the model year · Seats and restraints
17 Sep 2026	Transport Canada recall 2026442 ^[2] Issued for the model year · High voltage
26 Oct 2026	Listed for sale, Calgary, AB ^[5] Auto Avenue · asking \$23,977

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 3 live listings, as of 26 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 26 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

