Register entry, as of 27 October 2026 Listed for sale Record ID 7a989fc5ab48

2017 Land Rover Discovery Sport HSE

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

SAL	CR2BG	0	H	H	672462
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jaguar Land Rover Limited	Discovery Sport · 2.0 L	Computes	2017	Halewood	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	2.0 L, 4 cylinders
Make	Land Rover	Fuel	Gasoline
Model	Discovery Sport	Drive	Not in the decode
Trim	HSE	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Halewood, England

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/discovery-sport/2017

3 recalls listed by Transport Canada for this model year

Steering

2018180 12 Apr 2018

On certain vehicles originally sold, or currently registered in areas of heavy road salt usage during winter months (Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador), the bolts that attach the power steering gear assist motor to the gear housing may corrode and fracture. This could allow the power steering gear assist motor to move, causing the belt to slip which could result in a loss of power steering assist. A loss of power steering assist would require additional steering effort which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the aluminum mounting bolts with coated steel bolts and will apply a corrosion-preventative sealer around the gear housing and connecting bolts. If a bolt is found to be broken or breaks during the course of the repair, a replacement steering gear will be installed.

Seats and restraints

2016653 22 Dec 2016

Certain vehicles may have been equipped with front seat belt pretensioners that do not meet specifications. This could cause the pretensioners to fail to deploy in the event of a crash, which could increase the risk of injury to the front seat occupants. Correction: Dealers will check the production date of the front seat belt assemblies (which incorporate the pretensioners) and replace as necessary.

Steering

2016615 8 Dec 2016

On certain vehicles, the front lower control arm ball joints may fail due to a manufacturing process error. if this occurs, the knuckle could separate from the front lower control arm, which could affect vehicle handling and increase the risk of a crash causing injury and/or damage to property. Correction : Dealers will inspect and replace the lower control arm to knuckle bolt and nut as necessary.

> Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
> Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
> www.landrover.ca/en/ownership/vin-recall.html

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $16,500[5], $1,605 over the median of $14,895[4].



Lowest ask	$11,999
Middle half	$13,800 – $17,477
Median ask	$14,895
This car	$16,500

Same configuration · 9 live listings · as of 27 Oct 2026

OTHER 2017 LAND ROVER DISCOVERY SPORT LISTINGS [5]

Smiths Falls, ON · 117,244 km	$17,502
Brampton, ON · 84,435 km	$14,444
Penticton, BC · 116,902 km	$15,987
Scarborough, ON · 125,460 km	$14,895
Edmonton, AB · 143,448 km	$16,250
Cobourg, ON · 153,809 km	$12,999

§4 EVENTS

2017	Model year 2017[1] Assembly plant Halewood, England
8 Dec 2016	Transport Canada recall 2016615[2] Issued for the model year · Steering
22 Dec 2016	Transport Canada recall 2016653[2] Issued for the model year · Seats and restraints
12 Apr 2018	Transport Canada recall 2018180[2] Issued for the model year · Steering
26 Oct 2026	Listed for sale, Edmonton, AB[5] North Edmonton Kia · asking $16,500
27 Oct 2026	Listing last updated[5] asking $16,500

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 9 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.