Register entry, as of 28 October 2026 Listed for sale Record ID 416d3e182d8a

2015 Land Rover Discovery Sport HSE LUX

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

SAL	CT2BG	7	F	H	516014
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jaguar Land Rover Limited	Discovery Sport · 2.0 L	Computes	2015	Halewood	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	2.0 L, 4 cylinders
Make	Land Rover	Fuel	Gasoline
Model	Discovery Sport	Drive	Not in the decode
Trim	HSE LUX	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Halewood, England

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/discovery-sport/2015

3 recalls listed by Transport Canada for this model year

Steering

2018180 12 Apr 2018

On certain vehicles originally sold, or currently registered in areas of heavy road salt usage during winter months (Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador), the bolts that attach the power steering gear assist motor to the gear housing may corrode and fracture. This could allow the power steering gear assist motor to move, causing the belt to slip which could result in a loss of power steering assist. A loss of power steering assist would require additional steering effort which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the aluminum mounting bolts with coated steel bolts and will apply a corrosion-preventative sealer around the gear housing and connecting bolts. If a bolt is found to be broken or breaks during the course of the repair, a replacement steering gear will be installed.

Powertrain

2016407 19 Aug 2016

On certain vehicles, the transmission wire harness connections may have been improperly crimped. This could cause an unexpected shift to neutral which could result in a loss of motive power, which in conjunction with traffic and road conditions, and the driver's reactions may increase the risk of a crash. Correction: Dealers will inspect the transmission serial number and, if required, update vehicle software to initiate "limp home mode" where the condition is detected.

Lights and instruments

2016200 5 May 2016

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard 108 - Lighting System and Retroreflective Devices. The rear license plate lamp housing may fall out and fail to illuminate the license plate properly as required by the standard. Correction: Dealers will replace both rear license plate lamp housings with an updated version.

> Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
> Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
> www.landrover.ca/en/ownership/vin-recall.html

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $12,991[5], $496 over the median of $12,495[4].

Lowest ask	$11,500
Middle half	$11,996 – $13,744
Median ask	$12,495
This car	$12,991

Same model year · 6 live listings · as of 28 Oct 2026

OTHER 2015 LAND ROVER DISCOVERY SPORT LISTINGS [5]

Calgary, AB · 145,300 km	$15,990
Ottawa, ON · 155,679 km	$11,999
Toronto, ON · 87,391 km	$11,500
Toronto, ON · 125,100 km	$13,995
Calgary, AB · 171,170 km	$11,995

§4 EVENTS

2015	Model year 2015[1] Assembly plant Halewood, England
5 May 2016	Transport Canada recall 2016200[2] Issued for the model year · Lights and instruments
19 Aug 2016	Transport Canada recall 2016407[2] Issued for the model year · Powertrain
12 Apr 2018	Transport Canada recall 2018180[2] Issued for the model year · Steering
25 Oct 2026	Listed for sale, London, ON[5] Downtown Motor Products · asking $12,991
28 Oct 2026	Listing last updated[5] asking $12,991

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 6 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.