Register entry, as of 23 November 2026 Listed for sale Record ID 0dee7c49af9f

2024 Land Rover Defender 110 S

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

SAL	EJ7EX	9	R	2	310045
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jaguar Land Rover Limited	Defender · 2.0 L	Computes	2024	Nitra	Build sequence

§1 IDENTITY [1]

Model year	2024	Engine	2.0 L, 4 cylinders
Make	Land Rover	Fuel	Gasoline
Model	Defender	Drive	AWD
Trim	110 S	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Nitra, Slovakia

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/defender/2024

8 recalls listed by Transport Canada for this model year

Seats and restraints

2026458 24 Sep 2026

Issue: On certain vehicles, the second-row seat belt(s) may not have been stitched properly. As a result, the seat belt(s) may not hold a person in place during a crash. Additionally, the seat belt(s) may not properly secure a child seat. Note: The vehicle's lower universal anchorage system (UAS) is not affected by this defect and may still be used to secure a child seat. Safety Risk: A seat belt that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the second-row seat belt(s).

High voltage

2026442 17 Sep 2026

Issue: On certain vehicles, the DC/DC converter could fail. As a result, the 12 V battery would not charge and a red "Stop Safely Electrical Fault Detected" warning message would be displayed. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels and/or the vehicle's lights could turn off. Note: This recall is an expansion of Transport Canada recall no. 2026-196. Vehicles repaired under that recall don't require this repair. This recall only affects certain mild hybrid electric vehicles (MHEV). Safety Risk: A loss of power to the wheels could increase the risk of a crash. Exterior lights that don't work may make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle load balancing software.

Airbag

2026292 12 Jun 2026

Issue: On certain vehicles, the connector for the driver-front airbag in the steering wheel could corrode. As a result, the driver-front airbag may not inflate in a crash. Note: This problem would cause the airbag warning light to turn on. Safety Risk: An airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to apply grease to the driver's airbag connector terminals.

High voltage

2026196 17 Apr 2026

Issue: On certain vehicles, the DC/DC converter could fail. As a result, the 12 V battery would not charge and a red "Stop Safely Electrical Fault Detected" warning message would be displayed. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels and/or the vehicle's lights could turn off. Note: This recall only affects certain mild hybrid electric vehicles (MHEV). Safety Risk: A loss of power to the wheels could increase the risk of a crash. Exterior lights that don't work may make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail. The corrective actions for this recall are under development.

Visual system

2025015 16 Jan 2025

Issue: On certain vehicles, a software problem could cause the touch screen to remain blank when the vehicle is started. As a result, the rearview camera image would not appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Note: This recall only affects vehicles equipped with a 10-inch touch screen. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to update the touch screen software.

Accessories

2024739 5 Dec 2024

Issue: This recall is for raised air intakes installed on new vehicles or sold as a dealer accessory. On certain vehicles, the raised air intake may not have been attached properly. As a result, the raised air intake could loosen and detach while driving. Safety Risk: A raised air intake that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners in writing and advise you to take your vehicle to a dealership to secure the raised air intake.

2 more on the model-year record, cardog.app/tools/recalls/land-rover/defender/2024

> Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
> Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
> www.landrover.ca/en/ownership/vin-recall.html

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $59,900[5], $4,550 under the median of $64,450[4].



Lowest ask	$59,900
Middle half	$62,358 – $65,790
Median ask	$64,450
This car	$59,900

Same configuration · 14 live listings · as of 22 Nov 2026

OTHER 2024 LAND ROVER DEFENDER LISTINGS [5]

Nepean, ON · 52,818 km	$71,888
Richmond, BC · 26,285 km	$69,900
North Vancouver, BC · 32,302 km	$61,986
Richmond, BC · 19,149 km	$61,990
Richmond, BC · 16,541 km	$72,990
Richmond, BC · 35,159 km	$72,490

§4 EVENTS

2024	Model year 2024[1] Assembly plant Nitra, Slovakia
17 Jun 2024	Transport Canada recall 2024352[2] Issued for the model year · Engine
10 Oct 2024	Transport Canada recall 2024599[2] Issued for the model year · Engine
5 Dec 2024	Transport Canada recall 2024739[2] Issued for the model year · Accessories
16 Jan 2025	Transport Canada recall 2025015[2] Issued for the model year · Visual system
17 Apr 2026	Transport Canada recall 2026196[2] Issued for the model year · High voltage
12 Jun 2026	Transport Canada recall 2026292[2] Issued for the model year · Airbag
17 Sep 2026	Transport Canada recall 2026442[2] Issued for the model year · High voltage
24 Sep 2026	Transport Canada recall 2026458[2] Issued for the model year · Seats and restraints
20 Nov 2026	Listed for sale, Vaughan, ON[5] Toronto Auto Brokers · asking $59,900
23 Nov 2026	Listing last updated[5] asking $59,900

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 14 live listings, as of 22 Nov 2026

[5] Live public dealer listings on Cardog, as of 23 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.