Register entry, as of 23 November 2026 Listed for sale Record ID 88b8d7c03311

2017 Land Rover Range Rover HSE

3.0 L, 6 cylinders · Sport Utility Vehicle · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

SAL	GS2FK	X	H	A	335973
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jaguar Land Rover Limited	Range Rover · 3.0 L	Computes	2017	Solihull	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	3.0 L, 6 cylinders
Make	Land Rover	Fuel	Diesel
Model	Range Rover	Drive	Not in the decode
Trim	HSE	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Solihull, England

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/range-rover/2017

4 recalls listed by Transport Canada for this model year

Suspension

2025338 19 Jun 2025

Issue: On certain vehicles, the front suspension knuckles could crack and/or break. A front knuckle that breaks while driving could cause a sudden loss of vehicle control. Note: This recall is an expansion of N759 (Transport Canada recall no. 2022-668). Certain vehicles that were inspected/repaired under that recall, also require this repair. Safety Risk: A loss of vehicle control could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to inspect the front suspension knuckles. If the knuckles aren't cracked, the dealer will install retaining brackets. If cracks are found, the dealer will replace the knuckle(s).

Engine

2018274 23 May 2018

On certain vehicles equipped with a diesel engine, a software issue could cause the fuel gauge to display a low fuel level and turn on the low fuel light, even though the fuel tank is not nearing empty. This could cause the engine management system to wrongly shut off the engine to protect it from what it interprets as a low fuel condition. This would result in a loss of vehicle propulsion and a loss of power braking assist, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will update the vehicle software.

Lights and instruments

2017525 26 Oct 2017

On certain vehicles, the instrument cluster could go blank intermittently and be unable to display important information. This could result in the driver not being aware of vehicle speed or any malfunction lights turning on, which could affect vehicle performance and increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will update the vehicle software.

Seats and restraints

2016653 22 Dec 2016

Certain vehicles may have been equipped with front seat belt pretensioners that do not meet specifications. This could cause the pretensioners to fail to deploy in the event of a crash, which could increase the risk of injury to the front seat occupants. Correction: Dealers will check the production date of the front seat belt assemblies (which incorporate the pretensioners) and replace as necessary.

> Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
> Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
> www.landrover.ca/en/ownership/vin-recall.html

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $29,994[5], $7,527 under the median of $37,521[4].



Lowest ask	$26,995
Middle half	$32,900 – $44,999
Median ask	$37,521
This car	$29,994

Same model year · 13 live listings · as of 23 Nov 2026

OTHER 2017 LAND ROVER RANGE ROVER LISTINGS [5]

Richmond, BC · 100,937 km	$49,995
Burnaby, BC · 88,967 km	$34,750
Richmond, BC · 158,163 km	$29,990
Calgary, AB · 141,488 km	$36,500
Belleville, ON · 147,670 km	$32,900
Toronto, ON · 104,819 km	$26,995

§4 EVENTS

2017	Model year 2017[1] Assembly plant Solihull, England
22 Dec 2016	Transport Canada recall 2016653[2] Issued for the model year · Seats and restraints
26 Oct 2017	Transport Canada recall 2017525[2] Issued for the model year · Lights and instruments
23 May 2018	Transport Canada recall 2018274[2] Issued for the model year · Engine
19 Jun 2025	Transport Canada recall 2025338[2] Issued for the model year · Suspension
13 Nov 2026	Listed for sale, St-Eustache, QC[5] Auto Devenzo · asking $29,994

23 Nov 2026 **Listing last updated**[5]
asking $29,994

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 13 live listings, as of 23 Nov 2026
[5] Live public dealer listings on Cardog, as of 23 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.