Register entry, as of 23 November 2026 Listed for sale Record ID 39994744fd9b

2025 Land Rover Range Rover Autobiography

4.4 L, 8 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

SAL	K1BE9	0	S	A	294384
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jaguar Land Rover Limited	Range Rover · 4.4 L	Computes	2025	Solihull	Build sequence

§1 IDENTITY [1]

Model year	2025	Engine	4.4 L, 8 cylinders
Make	Land Rover	Fuel	Gasoline
Model	Range Rover	Drive	AWD
Trim	Autobiography	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Solihull, United Kingdom

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/range-rover/2025

6 recalls listed by Transport Canada for this model year

Visual system

2026498 15 Oct 2026

Issue: On certain vehicles, water could leak into the rearview camera and cause the rearview camera image not to display properly or at all. Safety Risk: A rearview camera image that doesn't display properly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the rearview camera. The dealer will also add drainage holes to the tailgate trim.

Airbag

2026292 12 Jun 2026

Issue: On certain vehicles, the connector for the driver-front airbag in the steering wheel could corrode. As a result, the driver-front airbag may not inflate in a crash. Note: This problem would cause the airbag warning light to turn on. Safety Risk: An airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to apply grease to the driver's airbag connector terminals.

Structure

2026074 19 Feb 2026

Issue: On certain vehicles, the side trim(s) on the panoramic sunroof may not be properly attached. As a result, the trim(s) could loosen and separate from the vehicle. Safety Risk: Trim that detaches from the vehicle could create a hazard for others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to secure the panoramic roof side trims.

Lights and instruments

2025565 16 Oct 2025

Issue: On certain vehicles, the gear shift module may not have been manufactured properly. As a result, the transmission gear selection indicator (PRND) displayed next to the shifter may not work. Safety Risk: A transmission gear selection indicator that doesn't work could create confusion and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to replace the gear shift module.

Seats and restraints

2025125 12 Mar 2025

Issue: On certain vehicles, the second-row center seat belt buckle may not have been manufactured properly. As a result, the seat belt may not latch securely. Safety Risk: A seat belt that doesn't latch properly could increase the risk of injury in a crash. Corrective Actions: To reduce the safety risk, Land Rover advises that you should check that the second-row center seat belt is latched properly. Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to replace the second-row center seat belt buckle.

Engine

2024599 10 Oct 2024


Issue: This recall is for certain replacement engines. The oil filter housing may not have been manufactured properly. Over time, the housing could crack and cause oil to leak onto hot components in the engine compartment. Safety Risk: Oil that leaks onto hot components can create the risk of a fire. Additionally, an oil leak could create a hazard for others and increase the risk of a crash. Corrective Actions: None of the affected engines have been installed in vehicles. Land Rover will instruct dealers to replace the oil filter housing assembly before each engine is installed.

> Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
> Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
> www.landrover.ca/en/ownership/vin-recall.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $178,998[5], $22,250 over the median of $156,748[4].



Lowest ask	$133,887
Middle half	$147,744 – $168,508
Median ask	$156,748
This car	$178,998

Same model year · 18 live listings · as of 23 Nov 2026

OTHER 2025 LAND ROVER RANGE ROVER LISTINGS [5]

Richmond Hill, ON · 17,500 km	$146,998
Richmond, BC · 4,030 km	$141,990
Calgary, AB · 15,212 km	$146,300
Calgary, AB · 14,471 km	$157,500
St-Eustache, QC · 5,661 km	$159,995
Vancouver, ON · 18,136 km	$151,995

§4 EVENTS

2025 Model year 2025[1]
Assembly plant Solihull, United Kingdom

10 Oct 2024	**Transport Canada recall 2024599**[2] Issued for the model year · Engine
12 Mar 2025	**Transport Canada recall 2025125**[2] Issued for the model year · Seats and restraints
16 Oct 2025	**Transport Canada recall 2025565**[2] Issued for the model year · Lights and instruments
19 Feb 2026	**Transport Canada recall 2026074**[2] Issued for the model year · Structure
12 Jun 2026	**Transport Canada recall 2026292**[2] Issued for the model year · Airbag
15 Oct 2026	**Transport Canada recall 2026498**[2] Issued for the model year · Visual system
22 Nov 2026	**Listed for sale, Richmond Hill, ON**[5] Jaguar/Land Rover Thornhill Certified Pre-Owned Center · asking $178,998

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 18 live listings, as of 23 Nov 2026

[5] Live public dealer listings on Cardog, as of 23 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.