

2025 Land Rover Range Rover Autobiography

4.4 L, 8 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER ^[1]

SAL **K1BE9** **2** **S** **A** **270863**

WMI 1-3

Jaguar Land Rover Limited

DESCRIPTOR 4-8

Range Rover · 4.4 L

CHECK 9

Computes

YEAR 10

2025

PLANT 11

Solihull

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2025	Engine	4.4 L, 8 cylinders
Make	Land Rover	Fuel	Gasoline
Model	Range Rover	Drive	AWD
Trim	Autobiography	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Solihull, United Kingdom

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/land-rover/range-rover/2025

5 recalls listed by Transport Canada for this model year

Airbag	2026292	12 Jun 2026
Issue: On certain vehicles, the connector for the driver-front airbag in the steering wheel could corrode. As a result, the driver-front airbag may not inflate in a crash. Note: This problem would cause the airbag warning light to turn on. Safety Risk: An airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to apply grease to the driver's airbag connector terminals.		
Structure	2026074	19 Feb 2026
Issue: On certain vehicles, the side trim(s) on the panoramic sunroof may not be properly attached. As a result, the trim(s) could loosen and separate from the vehicle. Safety Risk: Trim that detaches from the vehicle could create a hazard for others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to secure the panoramic roof side trims.		
Lights and instruments	2025565	16 Oct 2025
Issue: On certain vehicles, the gear shift module may not have been manufactured properly. As a result, the transmission gear selection indicator (PRND) displayed next to the shifter may not work. Safety Risk: A transmission gear selection indicator that doesn't work could create confusion and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to replace the gear shift module.		



Seats and restraints

2025125 12 Mar 2025

Issue: On certain vehicles, the second-row center seat belt buckle may not have been manufactured properly. As a result, the seat belt may not latch securely. Safety Risk: A seat belt that doesn't latch properly could increase the risk of injury in a crash. Corrective Actions: To reduce the safety risk, Land Rover advises that you should check that the second-row center seat belt is latched properly. Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to replace the second-row center seat belt buckle.

Engine

2024599 10 Oct 2024

Issue: This recall is for certain replacement engines. The oil filter housing may not have been manufactured properly. Over time, the housing could crack and cause oil to leak onto hot components in the engine compartment. Safety Risk: Oil that leaks onto hot components can create the risk of a fire. Additionally, an oil leak could create a hazard for others and increase the risk of a crash. Corrective Actions: None of the affected engines have been installed in vehicles. Land Rover will instruct dealers to replace the oil filter housing assembly before each engine is installed.

Listed for the model year, not checked against your VIN. Land Rover confirms which apply.

Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.

www.landrover.ca/en/ownership/vin-recall.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$179,900^[5], \$19,902 over the median of \$159,998^[4].



Lowest ask	\$133,987
Middle half	\$149,998 – \$179,900
Median ask	\$159,998
This car	\$179,900

Same model year · 13 live listings · as of 29 Oct 2026

OTHER 2025 LAND ROVER RANGE ROVER LISTINGS [5]

Oakville, ON · 8,322 km	\$157,790
Richmond Hill, ON · 13,100 km	\$167,998
Ajax, ON · 26,123 km	\$133,987
Richmond Hill, ON · 6,010 km	\$159,998
Oakville, ON · 13,217 km	\$278,800

§4 EVENTS

2025	Model year 2025 ^[1] Assembly plant Solihull, United Kingdom
10 Oct 2024	Transport Canada recall 2024599 ^[2] Issued for the model year · Engine
12 Mar 2025	Transport Canada recall 2025125 ^[2] Issued for the model year · Seats and restraints
16 Oct 2025	Transport Canada recall 2025565 ^[2] Issued for the model year · Lights and instruments



19 Feb 2026	Transport Canada recall 2026074 ^[2] Issued for the model year · Structure
12 Jun 2026	Transport Canada recall 2026292 ^[2] Issued for the model year · Airbag
28 Oct 2026	Listed for sale, Montréal, QC ^[5] Rolls-Royce Motor Cars Quebec · asking \$179,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 13 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

