Register entry, as of 28 October 2026 Listed for sale Record ID a595970e08bb

2023 Land Rover Range Rover SE

4.4 L, 8 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

SAL	KP9E7	1	P	A	059070
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jaguar Land Rover Limited	Range Rover · 4.4 L	Computes	2023	Solihull	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	4.4 L, 8 cylinders
Make	Land Rover	Fuel	Gasoline
Model	Range Rover	Drive	AWD
Trim	SE	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Solihull, United Kingdom

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/range-rover/2023

10 recalls listed by Transport Canada for this model year

High voltage

2026442 17 Sep 2026

Issue: On certain vehicles, the DC/DC converter could fail. As a result, the 12 V battery would not charge and a red "Stop Safely Electrical Fault Detected" warning message would be displayed. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels and/or the vehicle's lights could turn off. Note: This recall is an expansion of Transport Canada recall no. 2026-196. Vehicles repaired under that recall don't require this repair. This recall only affects certain mild hybrid electric vehicles (MHEV). Safety Risk: A loss of power to the wheels could increase the risk of a crash. Exterior lights that don't work may make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle load balancing software.

Airbag

2026292 12 Jun 2026

Issue: On certain vehicles, the connector for the driver-front airbag in the steering wheel could corrode. As a result, the driver-front airbag may not inflate in a crash. Note: This problem would cause the airbag warning light to turn on. Safety Risk: An airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to apply grease to the driver's airbag connector terminals.

High voltage

2026196 17 Apr 2026

Issue: On certain vehicles, the DC/DC converter could fail. As a result, the 12 V battery would not charge and a red "Stop Safely Electrical Fault Detected" warning message would be displayed. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels and/or the vehicle's lights could turn off. Note: This recall only affects certain mild hybrid electric vehicles (MHEV). Safety Risk: A loss of power to the wheels could increase the risk of a crash. Exterior lights that don't work may make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail. The corrective actions for this recall are under development.

Structure
2026074 19 Feb 2026

Issue: On certain vehicles, the side trim(s) on the panoramic sunroof may not be properly attached. As a result, the trim(s) could loosen and separate from the vehicle. Safety Risk: Trim that detaches from the vehicle could create a hazard for others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to secure the panoramic roof side trims.

Visual system
2024769 19 Dec 2024

Issue: On certain vehicles, water could leak into the rearview camera and cause the rearview camera image not to display correctly or at all. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to replace the rearview camera.

Engine
2024599 10 Oct 2024

Issue: This recall is for certain replacement engines. The oil filter housing may not have been manufactured properly. Over time, the housing could crack and cause oil to leak onto hot components in the engine compartment. Safety Risk: Oil that leaks onto hot components can create the risk of a fire. Additionally, an oil leak could create a hazard for others and increase the risk of a crash. Corrective Actions: None of the affected engines have been installed in vehicles. Land Rover will instruct dealers to replace the oil filter housing assembly before each engine is installed.

4 more on the model-year record, cardog.app/tools/recalls/land-rover/range-rover/2023

> Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
> Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
> www.landrover.ca/en/ownership/vin-recall.html

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $115,900[5], $3,458 over the median of $112,442[4].

Lowest ask	$91,777
Middle half	$105,897 – $118,371
Median ask	$112,442
This car	$115,900

Same configuration · 16 live listings · as of 28 Oct 2026

OTHER 2023 LAND ROVER RANGE ROVER LISTINGS [5]

Leamington, ON · 79,642 km	$106,000
Montréal, QC · 59,316 km	$125,995
Essex, ON · 79,642 km	$106,000
Toronto, ON · 79,642 km	$106,000
Saskatoon, SK · 42,950 km	$115,990
Windsor, ON · 79,642 km	$106,000

§4 EVENTS

2023 Model year 2023[1]
Assembly plant Solihull, United Kingdom

2 Feb 2023	Transport Canada recall 2023037[2] Issued for the model year · Visual system
6 Apr 2023	Transport Canada recall 2023209[2] Issued for the model year · Seats and restraints
4 May 2023	Transport Canada recall 2023269[2] Issued for the model year · Accessories
1 Jun 2023	Transport Canada recall 2023317[2] Issued for the model year · Lights and instruments
10 Oct 2024	Transport Canada recall 2024599[2] Issued for the model year · Engine
19 Dec 2024	Transport Canada recall 2024769[2] Issued for the model year · Visual system
19 Feb 2026	Transport Canada recall 2026074[2] Issued for the model year · Structure
17 Apr 2026	Transport Canada recall 2026196[2] Issued for the model year · High voltage
1 Jun 2026	Listed for sale, Laval, QC[5] Jaguar Land Rover Laval · asking $115,900
12 Jun 2026	Transport Canada recall 2026292[2] Issued for the model year · Airbag
17 Sep 2026	Transport Canada recall 2026442[2] Issued for the model year · High voltage
27 Oct 2026	Listing last updated[5] asking $115,900

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 16 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.