Register entry, as of 27 October 2026 Listed for sale Record ID 50155b06e541

2019 Land Rover Discovery SE

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

SAL	RG2RV	1	K	2	412442
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jaguar Land Rover Limited	Discovery · 3.0 L	Computes	2019	Nitra	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	3.0 L, 6 cylinders
Make	Land Rover	Fuel	Gasoline
Model	Discovery	Drive	AWD
Trim	SE	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Nitra, Slovakia

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/discovery/2019

4 recalls listed by Transport Canada for this model year

Structure — 2025315 — 12 Jun 2025

Issue: On certain vehicles, the rear doors may not latch properly when they are closed. As a result, the rear doors could open while driving. Safety Risk: A door that opens suddenly while driving could create the risk of injury and/or increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to disable the unilatch keyless vehicle (KV) entry function.

Lights and instruments — 2021102 — 25 Feb 2021

Issue: On certain vehicles, when the Automatic High Beam (AHB) system is turned on, the AHB tell-tale indicator on the instrument panel may not turn on. This could lead you to drive without knowing that high beam lights can turn on automatically. Canadian regulations require a tell-tale indicator to turn on when the automatic high beams are activated. Safety Risk: A driver that does not know that the high beam lights are turned on could create glare for other drivers and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and instruct you to take your vehicle to a dealer to update vehicle software.

Electrical — 2020533 — 10 Nov 2020

Issue: On certain vehicles, the ground connection for the battery may not be properly attached to the chassis. This could cause various electrical problems. As a result, there could be a loss of electrical power while driving, which could cause the engine to turn off. Safety Risk: A loss of power while driving could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and instruct you to take your vehicle to a dealer to replace the battery ground stud on the chassis.

Other — 2019588 — 20 Nov 2019

Issue: One vehicle was produced and delivered with an incorrect vehicle identification number (VIN). Safety Risk: Canadian regulations have strict requirements for the VIN that must be followed. Corrective Actions: Land Rover has removed the affected vehicle from the market.

> Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
> Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
> www.landrover.ca/en/ownership/vin-recall.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $20,988[5], $5,014 under the median of $26,002[4].

Lowest ask	$20,988
Middle half	$23,915 – $28,971
Median ask	$26,002
This car	$20,988

Same model year · 10 live listings · as of 27 Oct 2026

OTHER 2019 LAND ROVER DISCOVERY LISTINGS [5]

Calgary, AB · 79,358 km	$24,998
Boisbriand, QC · 98,000 km	$15,995
Nanaimo, BC · 130,768 km	$23,888
Calgary, AB · 134,505 km	$23,995
Sherwood Park, AB · 86,585 km	$28,900
Langley, BC · 103,308 km	$27,005

§4 EVENTS

2019	Model year 2019[1] Assembly plant Nitra, Slovakia
20 Nov 2019	Transport Canada recall 2019588[2] Issued for the model year · Other
10 Nov 2020	Transport Canada recall 2020533[2] Issued for the model year · Electrical
25 Feb 2021	Transport Canada recall 2021102[2] Issued for the model year · Lights and instruments
12 Jun 2025	Transport Canada recall 2025315[2] Issued for the model year · Structure
15 Jul 2026	Listed for sale, Oakville, ON[5] Oakville Chrysler Dodge Jeep Ram Ltd. · asking $20,988
27 Oct 2026	Listing last updated[5] asking $20,988

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 10 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.