

Register entry, as of 29 October 2026

Listed for sale

Record ID 28e8a2f4760b

2018 Land Rover Range Rover Sport HSE

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

SAL **WR2RK** **X** **J** **A** **196503**

WMI 1-3

Jaguar Land Rover Limited

DESCRIPTOR 4-8

Range Rover Sport · 3.0 L

CHECK 9

Computes

YEAR 10

2018

PLANT 11

Solihull

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.0 L, 6 cylinders
Make	Land Rover	Fuel	Diesel
Model	Range Rover Sport	Drive	AWD
Trim	HSE	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Solihull, United Kingdom

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/range-rover-sport/2018

4 recalls listed by Transport Canada for this model year

Visual system

2024289 23 May 2024

Issue: On certain Ranger Rover Sport models, the recall repairs completed by a Land Rover dealer during recall N778 (Transport Canada recall no. 2024-017) may not have been done correctly. As a result, a second repair is required. On certain vehicles, water could leak into the rearview camera and cause the rearview camera image not to display correctly. Note: This recall only affects vehicles equipped with a surround camera system. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to inspect the rearview camera and install a new seal. The dealer will replace the rearview camera, if necessary.

Visual system

2024017 18 Jan 2024

For Ranger Rover Sport models, this recall was replaced by Transport Canada recall no. 2024-289. Issue: On certain vehicles, water could leak into the rearview camera and cause the rearview camera image not to display correctly. Note: This recall only affects vehicles equipped with a surround camera system. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to inspect the rearview camera and install a new seal. The dealer will replace the rearview camera, if necessary.

Lights and instruments

2021102 25 Feb 2021

Issue: On certain vehicles, when the Automatic High Beam (AHB) system is turned on, the AHB tell-tale indicator on the instrument panel may not turn on. This could lead you to drive without knowing that high beam lights can turn on automatically. Canadian regulations require a tell-tale indicator to turn on when the automatic high beams are activated. Safety Risk: A driver that does not know that the high beam lights are turned on could create glare for other drivers and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and instruct you to take your vehicle to a dealer to update vehicle software.



Brakes

2018499 13 Sep 2018


On certain vehicles, the Autonomous Emergency Braking (AEB) system is inoperative with no warning to the driver. In the event of a potential collision, the AEB would not activate as intended, which could increase the risk of injury and/or damage to property. Correction: Dealers will update the AEB software.

Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
www.landrover.ca/en/ownership/vin-recall.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$30,990^[5], the median^[4].



Lowest ask	\$25,995
Middle half	\$28,999 – \$34,999
Median ask	\$30,990
This car	\$30,990

Same configuration · 9 live listings · as of 29 Oct 2026

OTHER 2018 LAND ROVER RANGE ROVER SPORT LISTINGS ^[5]

North York, ON · 40,000 km	\$34,999
Calgary, AB · 60,941 km	\$33,995
North York, ON · 135,000 km	\$26,499
North York, ON · 64,248 km	\$39,985
Richmond, BC · 85,718 km	\$56,995
Georgetown, ON · 83,947 km	\$30,950

§4 EVENTS

2018	Model year 2018 ^[1] Assembly plant Solihull, United Kingdom
13 Sep 2018	Transport Canada recall 2018499 ^[2] Issued for the model year · Brakes
25 Feb 2021	Transport Canada recall 2021102 ^[2] Issued for the model year · Lights and instruments
18 Jan 2024	Transport Canada recall 2024017 ^[2] Issued for the model year · Visual system
23 May 2024	Transport Canada recall 2024289 ^[2] Issued for the model year · Visual system
8 Jul 2026	Listed for sale, Laval, QC ^[5] Sélection Auto Direct · asking \$30,990



28 Oct 2026 Listing last updated^[5]
asking \$30,990

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 9 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

