Register entry, as of 29 October 2026 Listed for sale Record ID ea4a6c71ef25

2015 Land Rover Range Rover Sport HSE

3.0 L, 6 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

SAL	WR2VF	2	F	A	606095
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Jaguar Land Rover Limited	Range Rover Sport · 3.0 L	Computes	2015	Solihull	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	3.0 L, 6 cylinders
Make	Land Rover	Fuel	Gasoline
Model	Range Rover Sport	Drive	Not in the decode
Trim	HSE	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Solihull, England

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/range-rover-sport/2015

8 recalls listed by Transport Canada for this model year

Suspension — 2025274 — 22 May 2025

Issue: On certain vehicles, the front suspension knuckles could crack and/or break. A front knuckle that breaks while driving could cause a sudden loss of vehicle control. Safety Risk: A loss of vehicle control could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to inspect the front suspension knuckles. If the knuckles aren't cracked, the dealer will install retaining brackets. If cracks are found, the dealer will replace the knuckle(s).

Structure — 2025027 — 23 Jan 2025

Issue: On certain vehicles, the doors may not latch properly when they are closed. As a result, the doors could open while driving. Safety Risk: A door that opens suddenly while driving could create the risk of injury and/or increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to update the unilatch keyless vehicle (KV) software.

Steering — 2019473 — 26 Sep 2019

Issue: On certain vehicles, the bolts that attach the electric power steering assist motor to the steering gear may corrode and break. This could cause a loss of power steering assist. This recall applies to vehicles originally sold or currently registered in areas of heavy road salt usage (Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador). Safety Risk: A loss of power steering assist may result in a sudden increase in steering effort, especially at low vehicle speeds. This could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the aluminum bolts with steel ones and apply a wax sealer. If a bolt is found broken or breaks during the repair, a replacement steering rack will be installed.

Accessories

2015424 24 Sep 2015

On certain vehicles, the backrest of the manual reclining second row seat system may not latch properly. If this occurs, the seat belt may not correctly restrain the occupant which could increase the risk of injury in the event of a crash. Correction: Dealers will inspect and replace the latching mechanism as necessary.

Structure

2015259 11 Jun 2015

On certain vehicles, if doors fail to latch properly in the primary or secondary closed position, there would be no indication provided to vehicle occupants of the unlatched door condition. This could result in a door opening while the vehicle is in motion, which could increase the risk of injury to a vehicle occupant seated next to the door, or result in damage to property. Correction: Dealers will update the vehicle software.

Airbag

2015077 19 Feb 2015

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 208 - Occupant Protection. The passenger seat occupant classification system (OCS) may have been calibrated incorrectly during the manufacturing process. This could result in the non-deployment of an airbag, which would increase the risk of injury to the seat occupant in a crash where airbag deployment is warranted. Correction: Dealers will reprogram the occupant classification system (OCS).

2 more on the model-year record, cardog.app/tools/recalls/land-rover/range-rover-sport/2015

> Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
> Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
> www.landrover.ca/en/ownership/vin-recall.html

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $19,895[5], $4,027 under the median of $23,922[4].

Lowest ask	$16,400
Middle half	$22,619 – $26,621
Median ask	$23,922
This car	$19,895

Same model year · 14 live listings · as of 29 Oct 2026

OTHER 2015 LAND ROVER RANGE ROVER SPORT LISTINGS [5]

Burnaby, BC · 130,791 km	$23,850
Airdrie, AB · 144,103 km	$23,995
Montréal, QC · 145,000 km	$17,995
Coquitlam, BC · 125,333 km	$28,997
North Vancouver District, BC · 125,645 km	$16,500
North Vancouver, BC · 125,645 km	$16,400

§4 EVENTS

2015 Model year 2015[1]
Assembly plant Solihull, England

18 Feb 2015	Transport Canada recall 2015072[2] Issued for the model year · Engine
19 Feb 2015	Transport Canada recall 2015077[2] Issued for the model year · Airbag
19 Feb 2015	Transport Canada recall 2015076[2] Issued for the model year · Wheels
11 Jun 2015	Transport Canada recall 2015259[2] Issued for the model year · Structure
24 Sep 2015	Transport Canada recall 2015424[2] Issued for the model year · Accessories
26 Sep 2019	Transport Canada recall 2019473[2] Issued for the model year · Steering
23 Jan 2025	Transport Canada recall 2025027[2] Issued for the model year · Structure
22 May 2025	Transport Canada recall 2025274[2] Issued for the model year · Suspension
16 Sep 2026	Listed for sale, North Vancouver, BC[5] Lexa Auto Sales Ltd. · asking $19,895
29 Oct 2026	Listing last updated[5] asking $19,895

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 14 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.