Register entry, as of 29 October 2026 Listed for sale Record ID 04d47da2da00

# 2017 Land Rover Range Rover Sport HSE Dynamic

3.0 L, 6 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| SAL | WV2FV | 6 | H | A | 150557 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Jaguar Land Rover Limited | Range Rover Sport · 3.0 L | Computes | 2017 | Solihull | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2017 | Engine | 3.0 L, 6 cylinders |
| Make | Land Rover | Fuel | Gasoline |
| Model | Range Rover Sport | Drive | Not in the decode |
| Trim | HSE Dynamic | Maker | JAGUAR LAND ROVER LIMITED |
| Body | Sport Utility Vehicle | Plant | Solihull, England |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/range-rover-sport/2017

**4** recalls listed by Transport Canada for this model year

### Suspension

2025274 22 May 2025

Issue: On certain vehicles, the front suspension knuckles could crack and/or break. A front knuckle that breaks while driving could cause a sudden loss of vehicle control. Safety Risk: A loss of vehicle control could increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to inspect the front suspension knuckles. If the knuckles aren't cracked, the dealer will install retaining brackets. If cracks are found, the dealer will replace the knuckle(s).

### Engine

2018274 23 May 2018

On certain vehicles equipped with a diesel engine, a software issue could cause the fuel gauge to display a low fuel level and turn on the low fuel light, even though the fuel tank is not nearing empty. This could cause the engine management system to wrongly shut off the engine to protect it from what it interprets as a low fuel condition. This would result in a loss of vehicle propulsion and a loss of power braking assist, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will update the vehicle software.

### Lights and instruments

2017525 26 Oct 2017

On certain vehicles, the instrument cluster could go blank intermittently and be unable to display important information. This could result in the driver not being aware of vehicle speed or any malfunction lights turning on, which could affect vehicle performance and increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will update the vehicle software.

### Seats and restraints

2016653 22 Dec 2016

Certain vehicles may have been equipped with front seat belt pretensioners that do not meet specifications. This could cause the pretensioners to fail to deploy in the event of a crash, which could increase the risk of injury to the front seat occupants. Correction: Dealers will check the production date of the front seat belt assemblies (which incorporate the pretensioners) and replace as necessary.

Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
www.landrover.ca/en/ownership/vin-recall.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $19,800[5], $6,198 under the median of $25,998[4].

| | |
|---|---|
| Lowest ask | $16,888 |
| Middle half | $22,746 – $28,999 |
| Median ask | $25,998 |
| This car | $19,800 |

Same model year · 28 live listings · as of 28 Oct 2026

OTHER 2017 LAND ROVER RANGE ROVER SPORT LISTINGS [5]

| | |
|---|---|
| Newmarket, ON · 150,626 km | $16,888 |
| Newmarket, ON · 150,626 km | $18,888 |
| London, ON · 156,064 km | $25,995 |
| Sylvan Lake, AB · 67,613 km | US$59,777 |
| Hamilton, ON · 107,149 km | $35,999 |
| Saint-Bruno-de-Montarville, QC · 150,000 km | $22,998 |

## §4 EVENTS

| | |
|---|---|
| 2017 | Model year 2017[1]<br>Assembly plant Solihull, England |
| 22 Dec 2016 | Transport Canada recall 2016653[2]<br>Issued for the model year · Seats and restraints |
| 26 Oct 2017 | Transport Canada recall 2017525[2]<br>Issued for the model year · Lights and instruments |
| 23 May 2018 | Transport Canada recall 2018274[2]<br>Issued for the model year · Engine |
| 22 May 2025 | Transport Canada recall 2025274[2]<br>Issued for the model year · Suspension |
| 24 Nov 2025 | Listed for sale, Burnaby, BC[5]<br>KNN AUTO Wholesale Limited · asking $19,800 |

| | |
|---|---|
| 27 Oct 2026 | Listing last updated[5]<br>asking $19,800 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We do not collect window stickers for this manufacturer. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 28 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.