Register entry, as of 29 October 2026 Listed for sale Record ID 7bcdd6556fb0

# 2021 Land Rover Range Rover Velar S

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| SAL | YJ2EX | 2 | M | A | 311245 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Jaguar Land Rover Limited | Range Rover Velar · 2.0 L | Computes | 2021 | Solihull | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2021 | Engine | 2.0 L, 4 cylinders |
| Make | Land Rover | Fuel | Gasoline |
| Model | Range Rover Velar | Drive | AWD |
| Trim | S | Maker | JAGUAR LAND ROVER LIMITED |
| Body | Sport Utility Vehicle | Plant | Solihull, United Kingdom |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/range-rover-velar/2021

**4** recalls listed by Transport Canada for this model year

### High voltage

2026442 17 Sep 2026

Issue: On certain vehicles, the DC/DC converter could fail. As a result, the 12 V battery would not charge and a red "Stop Safely Electrical Fault Detected" warning message would be displayed. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels and/or the vehicle's lights could turn off. Note: This recall is an expansion of Transport Canada recall no. 2026-196. Vehicles repaired under that recall don't require this repair. This recall only affects certain mild hybrid electric vehicles (MHEV). Safety Risk: A loss of power to the wheels could increase the risk of a crash. Exterior lights that don't work may make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and advise you to take your vehicle to a dealership to update the vehicle load balancing software.

### High voltage

2026196 17 Apr 2026

Issue: On certain vehicles, the DC/DC converter could fail. As a result, the 12 V battery would not charge and a red "Stop Safely Electrical Fault Detected" warning message would be displayed. If this happens, and you continue to drive the vehicle, there could be a loss of power to the wheels and/or the vehicle's lights could turn off. Note: This recall only affects certain mild hybrid electric vehicles (MHEV). Safety Risk: A loss of power to the wheels could increase the risk of a crash. Exterior lights that don't work may make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail. The corrective actions for this recall are under development.

### Engine

2024599 10 Oct 2024

Issue: This recall is for certain replacement engines. The oil filter housing may not have been manufactured properly. Over time, the housing could crack and cause oil to leak onto hot components in the engine compartment. Safety Risk: Oil that leaks onto hot components can create the risk of a fire. Additionally, an oil leak could create a hazard for others and increase the risk of a crash. Corrective Actions: None of the affected engines have been installed in vehicles. Land Rover will instruct dealers to replace the oil filter housing assembly before each engine is installed.

### Seats and restraints

2021533 26 Aug 2021

Issue: On certain vehicles, the passenger seat belt assemblies may contain defective automatic locking retractors (ALR). As a result, the seat belts may not properly lock to secure a child seat. Note: The vehicle's lower universal anchorage system (UAS) is not affected by this defect and may still be used to secure a child seat. Safety Risk: A seat belt that is used to secure a child restraint but is not properly locked could increase the risk of injury in a crash. Corrective Actions: Land Rover will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the seat belts. They will be replaced, if necessary.

Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
www.landrover.ca/en/ownership/vin-recall.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $28,888[5], $4,845 under the median of $33,733[4].

| | |
|---|---|
| Lowest ask | $27,888 |
| Middle half | $31,596 – $36,495 |
| Median ask | $33,733 |
| This car | $28,888 |

Same model year · 12 live listings · as of 28 Oct 2026

OTHER 2021 LAND ROVER RANGE ROVER VELAR LISTINGS [5]

| | |
|---|---|
| Vaughan, ON · 85,193 km | $32,900 |
| Mississauga, ON · 107,533 km | $30,899 |
| Leamington, ON · 107,533 km | $30,899 |
| Essex, ON · 107,533 km | $30,899 |
| Saskatoon, SK · 67,000 km | $34,471 |
| Toronto, ON · 107,533 km | $30,899 |

## §4 EVENTS

| | |
|---|---|
| 2021 | Model year 2021[1]<br>Assembly plant Solihull, United Kingdom |
| 26 Aug 2021 | Transport Canada recall 2021533[2]<br>Issued for the model year · Seats and restraints |
| 10 Oct 2024 | Transport Canada recall 2024599[2]<br>Issued for the model year · Engine |
| 17 Apr 2026 | Transport Canada recall 2026196[2]<br>Issued for the model year · High voltage |
| 17 Sep 2026 | Transport Canada recall 2026442[2]<br>Issued for the model year · High voltage |

| | |
|---|---|
| 19 Oct 2026 | Listed for sale, Concord, ON[5]<br>Cristal 2000 Auto Inc. · asking $28,888 |
| 26 Oct 2026 | Listing last updated[5]<br>asking $28,888 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 12 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.