Register entry, as of 27 October 2026 Listed for sale Record ID 2b556ff68c3a

2020 Land Rover Range Rover Velar

Sport Utility Vehicle

VEHICLE IDENTIFICATION NUMBER [1]

SAL	YK2FX	1	L	A	271993
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Jaguar Land Rover Limited	Range Rover Velar	Computes	2020	Solihull	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	Not in the decode
Make	Land Rover	Fuel	Not in the decode
Model	Range Rover Velar	Drive	Not in the decode
Trim	Not in the decode	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Solihull, United Kingdom

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/range-rover-velar/2020

2 recalls listed by Transport Canada for this model year

Seats and restraints

2021533 26 Aug 2021

Issue: On certain vehicles, the passenger seat belt assemblies may contain defective automatic locking retractors (ALR). As a result, the seat belts may not properly lock to secure a child seat. Note: The vehicle's lower universal anchorage system (UAS) is not affected by this defect and may still be used to secure a child seat. Safety Risk: A seat belt that is used to secure a child restraint but is not properly locked could increase the risk of injury in a crash. Corrective Actions: Land Rover will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the seat belts. They will be replaced, if necessary.

Lights and instruments

2021102 25 Feb 2021

Issue: On certain vehicles, when the Automatic High Beam (AHB) system is turned on, the AHB tell-tale indicator on the instrument panel may not turn on. This could lead you to drive without knowing that high beam lights can turn on automatically. Canadian regulations require a tell-tale indicator to turn on when the automatic high beams are activated. Safety Risk: A driver that does not know that the high beam lights are turned on could create glare for other drivers and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and instruct you to take your vehicle to a dealer to update vehicle software.

Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
www.landrover.ca/en/ownership/vin-recall.html

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $28,732[5], $555 under the median of $29,287[4].

Lowest ask	$20,500
Middle half	$28,243 – $29,967
Median ask	$29,287
This car	$28,732

Same configuration · 10 live listings · as of 27 Oct 2026

OTHER 2020 LAND ROVER RANGE ROVER VELAR LISTINGS [5]

Smiths Falls, ON · 87,235 km	$32,498
Kelowna, BC · 81,039 km	$31,802
Ottawa, ON · 129,321 km	$29,871
Toronto, ON · 104,000 km	$29,450
Toronto, ON · 137,000 km	$26,950
Georgetown, ON · 154,883 km	$20,500

§4 EVENTS

2020	Model year 2020[1] Assembly plant Solihull, United Kingdom
25 Feb 2021	Transport Canada recall 2021102[2] Issued for the model year · Lights and instruments
26 Aug 2021	Transport Canada recall 2021533[2] Issued for the model year · Seats and restraints
26 Oct 2026	Listed for sale, Montréal Nord, QC[5] autoxtreme.ca · asking $28,732

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 10 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.