Register entry, as of 29 October 2026 Listed for sale Record ID a798d57fbd63

# 2020 Land Rover Range Rover Velar

Sport Utility Vehicle

VEHICLE IDENTIFICATION NUMBER [1]

| SAL | YK2FX | 8 | L | A | 265415 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Jaguar Land Rover Limited | Range Rover Velar | Computes | 2020 | Solihull | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2020 | Engine | Not in the decode |
| Make | Land Rover | Fuel | Not in the decode |
| Model | Range Rover Velar | Drive | Not in the decode |
| Trim | Not in the decode | Maker | JAGUAR LAND ROVER LIMITED |
| Body | Sport Utility Vehicle | Plant | Solihull, United Kingdom |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/range-rover-velar/2020

**2** recalls listed by Transport Canada for this model year

### Seats and restraints

2021533 26 Aug 2021

Issue: On certain vehicles, the passenger seat belt assemblies may contain defective automatic locking retractors (ALR). As a result, the seat belts may not properly lock to secure a child seat. Note: The vehicle's lower universal anchorage system (UAS) is not affected by this defect and may still be used to secure a child seat. Safety Risk: A seat belt that is used to secure a child restraint but is not properly locked could increase the risk of injury in a crash. Corrective Actions: Land Rover will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the seat belts. They will be replaced, if necessary.

### Lights and instruments

2021102 25 Feb 2021

Issue: On certain vehicles, when the Automatic High Beam (AHB) system is turned on, the AHB tell-tale indicator on the instrument panel may not turn on. This could lead you to drive without knowing that high beam lights can turn on automatically. Canadian regulations require a tell-tale indicator to turn on when the automatic high beams are activated. Safety Risk: A driver that does not know that the high beam lights are turned on could create glare for other drivers and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and instruct you to take your vehicle to a dealer to update vehicle software.

Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
www.landrover.ca/en/ownership/vin-recall.html

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $29,575[5], the median[4].

| | |
|---|---|
| Lowest ask | $20,500 |
| Middle half | $28,492 – $30,747 |
| Median ask | $29,575 |
| This car | $29,575 |

Same configuration · 11 live listings · as of 28 Oct 2026

### OTHER 2020 LAND ROVER RANGE ROVER VELAR LISTINGS [5]

| | |
|---|---|
| Longueuil, QC · 158,572 km | $27,455 |
| Smiths Falls, ON · 87,235 km | $30,998 |
| Kelowna, BC · 81,039 km | $31,802 |
| Montréal Nord, QC · 106,446 km | $28,732 |
| Ottawa, ON · 129,321 km | $29,871 |
| Toronto, ON · 104,000 km | $29,450 |

## §4 EVENTS

| | |
|---|---|
| 2020 | Model year 2020[1]<br>Assembly plant Solihull, United Kingdom |
| 25 Feb 2021 | Transport Canada recall 2021102[2]<br>Issued for the model year · Lights and instruments |
| 26 Aug 2021 | Transport Canada recall 2021533[2]<br>Issued for the model year · Seats and restraints |
| 5 Sep 2026 | Listed for sale, Brampton, ON[5]<br>Frost Chevrolet Buick GMC Cadillac Ltd · asking $29,575 |
| 29 Oct 2026 | Listing last updated[5]<br>asking $29,575 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 11 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.