

2019 Land Rover Range Rover Velar R-Dynamic SE

2.0 L · AWD · Sport Utility Vehicle · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

SAL **YL2EN** **9** **K** **A** **213061**

WMI 1-3

Jaguar Land Rover Limited

DESCRIPTOR 4-8

Range Rover Velar · 2.0 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Solihull

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	2.0 L
Make	Land Rover	Fuel	Diesel
Model	Range Rover Velar	Drive	AWD
Trim	R-Dynamic SE	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Solihull, United Kingdom

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/range-rover-velar/2019

2 recalls listed by Transport Canada for this model year

Lights and instruments

2021102 25 Feb 2021

Issue: On certain vehicles, when the Automatic High Beam (AHB) system is turned on, the AHB tell-tale indicator on the instrument panel may not turn on. This could lead you to drive without knowing that high beam lights can turn on automatically. Canadian regulations require a tell-tale indicator to turn on when the automatic high beams are activated. Safety Risk: A driver that does not know that the high beam lights are turned on could create glare for other drivers and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and instruct you to take your vehicle to a dealer to update vehicle software.

Engine

2019029 17 Jan 2019

Issue: On certain vehicles, the engine crankshaft pulley bolt may have been manufactured improperly. This could cause it to crack and fail. If this happens, the crankshaft could break and cause a sudden engine failure. A driver may hear loud noises and see warning lights on the dash immediately before the engine fails. Safety Risk: An engine failure could increase the risk of a crash. Additionally, a loose pulley could separate from the engine and cause damage. If it separates from the vehicle, it could become a hazard for bystanders or other drivers. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to an authorized repair facility to have the crankshaft pulley bolt replaced with a new one.

Listed for the model year, not checked against your VIN. Land Rover confirms which apply.

Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.

www.landrover.ca/en/ownership/vin-recall.html



United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$24,999^[5], \$2,000 under the median of \$26,999^[4].



Lowest ask	\$23,000
Middle half	\$25,260 – \$29,907
Median ask	\$26,999
This car	\$24,999

Same model year · 17 live listings · as of 29 Oct 2026

OTHER 2019 LAND ROVER RANGE ROVER VELAR LISTINGS ^[5]

Calgary, AB · 102,287 km	\$26,290
Mississauga, ON · 108,399 km	\$28,400
Leamington, ON · 108,399 km	\$28,400
Essex, ON · 108,397 km	\$28,500
Toronto, ON · 108,397 km	\$28,500
Grande Prairie, AB · 82,792 km	\$25,260

§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Solihull, United Kingdom
17 Jan 2019	Transport Canada recall 2019029 ^[2] Issued for the model year · Engine
25 Feb 2021	Transport Canada recall 2021102 ^[2] Issued for the model year · Lights and instruments
24 Nov 2025	Listed for sale, Mississauga, ON ^[5] VAULT MOTORS · asking \$24,999
29 Oct 2026	Listing last updated ^[5] asking \$24,999

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 17 live listings, as of 29 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 29 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

