Register entry, as of 28 October 2026 Listed for sale Record ID 4bb921e546ac

2018 Land Rover Range Rover Velar R-Dynamic SE

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

SAL	YL2RV	8	J	A	761335
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jaguar Land Rover Limited	Range Rover Velar · 3.0 L	Computes	2018	Solihull	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.0 L, 6 cylinders
Make	Land Rover	Fuel	Gasoline
Model	Range Rover Velar	Drive	AWD
Trim	R-Dynamic SE	Maker	JAGUAR LAND ROVER LIMITED
Body	Sport Utility Vehicle	Plant	Solihull, United Kingdom

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/land-rover/range-rover-velar/2018

2 recalls listed by Transport Canada for this model year

Lights and instruments

2021102 25 Feb 2021

Issue: On certain vehicles, when the Automatic High Beam (AHB) system is turned on, the AHB tell-tale indicator on the instrument panel may not turn on. This could lead you to drive without knowing that high beam lights can turn on automatically. Canadian regulations require a tell-tale indicator to turn on when the automatic high beams are activated. Safety Risk: A driver that does not know that the high beam lights are turned on could create glare for other drivers and increase the risk of a crash. Corrective Actions: Land Rover will notify owners by mail and instruct you to take your vehicle to a dealer to update vehicle software.

Heater and defroster

2018107 1 Mar 2018

On certain vehicles, the heating, ventilation and air conditioning (HVAC) system air inlet door linkage may become detached. If this occurs, the HVAC unit may not work as intended, causing fog on the interior windows. This could reduce the driver's visibility, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will update the vehicle's software and replace the actuator arm.

> Listed for the model year, not checked against your VIN. Land Rover confirms which apply.
> Check your VIN with Land Rover Canada or call a Land Rover dealer with your VIN.
> www.landrover.ca/en/ownership/vin-recall.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $22,995[5], $3,925 under the median of $26,920[4].



Lowest ask	$16,999
Middle half	$23,496 – $31,497
Median ask	$26,920
This car	$22,995

Same model year · 15 live listings · as of 28 Oct 2026

OTHER 2018 LAND ROVER RANGE ROVER VELAR LISTINGS [5]

Calgary, AB · 134,382 km	$23,998
Saskatoon, SK · 99,140 km	$31,995
Oakville, ON · 123,739 km	$20,995
Winnipeg, MB · 59,095 km	$34,564
Winnipeg, MB · 59,095 km	$30,999
Coquitlam, BC · 113,898 km	$24,444

§4 EVENTS

2018	Model year 2018[1] Assembly plant Solihull, United Kingdom
1 Mar 2018	Transport Canada recall 2018107[2] Issued for the model year · Heater and defroster
25 Feb 2021	Transport Canada recall 2021102[2] Issued for the model year · Lights and instruments
20 Jun 2026	Listed for sale, Richmond, BC[5] UC AUTO LIMITED · asking $22,995
28 Oct 2026	Listing last updated[5] asking $22,995

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 15 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.