

Register entry, as of 27 October 2026

Listed for sale

Record ID 134464bb4c58

2025 Aston Martin DBX DBX707

4.0 L, 8 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

SD7 VUJDW 1 S T V13497

WMI 1-3

Aston Martin Lagonda Limi...

DESCRIPTOR 4-8

DBX · 4.0 L

CHECK 9

Computes

YEAR 10

2025

PLANT 11

St Athan

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2025	Engine	4.0 L, 8 cylinders
Make	Aston Martin	Fuel	Gasoline
Model	DBX	Drive	Not in the decode
Trim	DBX707	Maker	ASTON MARTIN LAGONDA LIMITED
Body	Sport Utility Vehicle	Plant	St Athan, South Wales, United Kingdom

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/aston-martin/dbx/2025

3 recalls listed by Transport Canada for this model year

Tires

2026153 1 Apr 2026

Issue: On certain vehicles, the tire pressure monitoring system (TPMS) warning light may not turn on when the tire pressure is low. Driving a vehicle with low tire pressure could lead to poor handling and/or a tire failure. Safety Risk: Poor handling or a tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: To reduce the safety risk, Aston Martin recommends that you should check the tire pressure and ensure that it matches the pressures listed on the tire and loading information label located inside the driver's door jamb. Aston Martin will notify owners by mail and advise you to take your vehicle to a dealership to update the TPMS software.

Suspension

2026156 31 Mar 2026

Issue: On certain vehicles, the pin(s) for the torque reaction link(s) may not have been manufactured correctly. As a result, the pin(s) could slide out of the rear lower suspension arm(s) and cause them to crack or break. If this happens, there could be a loss of vehicle control and/or damage to other suspension components and rear brakes. Safety Risk: A loss of vehicle control could increase the risk of a crash. Damaged brakes could cause extended stopping distances and increase the risk of a crash. Corrective Actions: Aston Martin will notify owners by mail and advise you to take your vehicle to a dealership to replace the rear torque reaction link bolts. The dealer will also inspect and replace any damaged parts, as necessary.

Visual system

2025026 22 Jan 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display properly. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display properly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Aston Martin will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the head unit software. Alternatively, you may schedule an appointment to have the update performed at an Aston Martin dealership.




Listed for the model year, not checked against your VIN. Aston Martin confirms which apply.
No online lookup from Aston Martin · call a Aston Martin dealer with your VIN.

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$259,995^[5], the median^[4].



Same model year · 1 live listings · as of 27 Oct 2026

§4 EVENTS

2025	Model year 2025 ^[1] Assembly plant St Athan, South Wales, United Kingdom
22 Jan 2025	Transport Canada recall 2025026 ^[2] Issued for the model year · Visual system
31 Mar 2026	Transport Canada recall 2026156 ^[2] Issued for the model year · Suspension
1 Apr 2026	Transport Canada recall 2026153 ^[2] Issued for the model year · Tires
9 Oct 2026	Listed for sale, Montréal, QC ^[5] Décarie Motors · asking \$259,995
26 Oct 2026	Listing last updated ^[5] asking \$259,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

