

Register entry, as of 27 October 2026

Listed for sale

Record ID 149dae73c9f8

2017 Infiniti QX30

2.0 L, 4 cylinders · 4WD · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

SJK **CH5CR** **5** **H** **A** **031504**

WMI 1-3

Infiniti · NISSAN MOTOR M...

DESCRIPTOR 4-8

QX30 · 2.0 L

CHECK 9

Computes

YEAR 10

2017

PLANT 11

Sunderland

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	2.0 L, 4 cylinders
Make	Infiniti	Fuel	Gasoline
Model	QX30	Drive	4WD
Trim	Not in the decode	Maker	NISSAN MOTOR MANUFACTURING (UK) LTD
Body	Hatchback	Plant	Sunderland, United Kingdom

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/infiniti/qx30/2017

4 recalls listed by Transport Canada for this model year

Steering

2021341 2 Jun 2021

Issue: On certain vehicles, the universal joint connection on the steering shaft could loosen over time. As a result, there could be noise or a change in steering feel. If a driver continues to operate the vehicle, the bearing could separate from the universal joint and cause a loss of steering control. Safety Risk: A loss of steering could create the risk of a crash. Corrective Actions: Infiniti will notify owners by mail and instruct you to take your vehicle to a dealer to replace the lower steering shaft.

Airbag

2017538 2 Nov 2017

On certain vehicles, electrostatic discharge, when combined with a broken clock spring and insufficient grounding of the steering components, could lead to an inadvertent deployment of the driver's frontal airbag. Unintended airbag deployment, in a non-warranted (non-impact) situation, could startle the driver, which could result in a crash causing injury and/or property damage. In some instances, inadvertent deployment could cause minor injuries to vehicle occupants. Correction: Dealers will add sufficient grounding to the steering components. Note: A broken clock spring would result in a driver airbag warning message appearing in the instrument cluster, as well as a red airbag warning lamp illuminating.

Airbag

2017115 7 Mar 2017

On certain vehicles, the generant mix ratio of the driver side curtain airbag may not meet specifications. In the event of a crash, an improper generant mix could prevent the side curtain airbag from deploying properly, which would increase the risk of injury to the driver. Correction: Dealers will replace the driver side curtain airbag assembly.



Airbag

2016649 22 Dec 2016

Certain vehicles may have been equipped with a passenger frontal airbag inflator that does not meet specifications. This could cause the passenger frontal airbag to fail to deploy in the event of a crash, which could increase the risk of injury to the occupants. Correction: Dealers will replace the passenger frontal airbag assembly.

Listed for the model year, not checked against your VIN. Infiniti confirms which apply.

Check your VIN with Infiniti Canada or call a Infiniti dealer with your VIN.

www.infiniti.ca/service/vin-recall.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$16,995^[5], \$1,847 over the median of \$15,148^[4].



Lowest ask	\$9,688
Middle half	\$12,336 – \$16,146
Median ask	\$15,148
This car	\$16,995

Same configuration · 8 live listings · as of 27 Oct 2026

OTHER 2017 INFINITI QX30 LISTINGS ^[5]

Kentville, NS · 185,054 km	\$9,688
Grande Prairie, AB · 121,012 km	\$16,609
Yarmouth, NS · 185,054 km	\$9,688
Middleton, NS · 185,054 km	\$9,688
Yarmouth, NS · 185,054 km	\$9,688
Grande Prairie, AB · 121,012 km	\$16,609

§4 EVENTS

2017	Model year 2017 ^[1] Assembly plant Sunderland, United Kingdom
22 Dec 2016	Transport Canada recall 2016649 ^[2] Issued for the model year · Airbag
7 Mar 2017	Transport Canada recall 2017115 ^[2] Issued for the model year · Airbag
2 Nov 2017	Transport Canada recall 2017538 ^[2] Issued for the model year · Airbag
2 Jun 2021	Transport Canada recall 2021341 ^[2] Issued for the model year · Steering
24 Jan 2026	Listed for sale, Toronto, ON ^[5] Ryder Auto Sales · asking \$16,995



24 Oct 2026 Listing last updated^[5]
asking \$16,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 8 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

