

Register entry, as of 29 October 2026

Listed for sale

Record ID 4adb8b17fb2b

2023 Rolls-Royce Cullinan Black Badge

6.8 L, 12 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER ^[1]**SLA TV8C0 9 P U 219476**

WMI 1-3

Rolls-Royce · ROLLS ROYC...

DESCRIPTOR 4-8

Cullinan · 6.8 L

CHECK 9

Computes

YEAR 10

2023

PLANT 11

Goodwood

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2023	Engine	6.8 L, 12 cylinders
Make	Rolls-Royce	Fuel	Gasoline
Model	Cullinan	Drive	AWD
Trim	Black Badge	Maker	ROLLS ROYCE MOTOR CARS
Body	Sport Utility Vehicle	Plant	Goodwood, England

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/rolls-royce/cullinan/2023

2 recalls listed by Transport Canada for this model year

Structure

2026113 12 Mar 2026

Issue: On a small number of vehicles, the bolts that secure the left and right rear seat belts or the locking brackets for the rear bench seat backrest may not have been tightened properly. As a result, the bolts could loosen and damage the seat belt webbing(s). Additionally, loose cargo in the luggage compartment could contact and move the rear bench seat backrest in a crash. Safety Risk: A seat belt that doesn't work properly and/or a seat backrest that moves could create an increased risk of injury in a crash. Additionally, cargo that moves in a crash could create a risk of injury. Corrective Action: To reduce the safety risk, Rolls-Royce recommends not using the rear seats to transport passengers or carrying cargo in the luggage compartment until the recall repairs have been completed. Rolls-Royce will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten or replace the bolts. Additionally, the dealer will inspect and, if necessary, replace the left and right rear seat belts.

Label

2024544 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Listed for the model year, not checked against your VIN. Rolls-Royce confirms which apply.

No online lookup from Rolls-Royce · call a Rolls-Royce dealer with your VIN.

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.^[3]



§3 VALUE [4]

This car asks \$419,900^[5], \$19,905 over the median of \$399,995^[4].



Lowest ask	\$399,995
Middle half	\$399,995 – \$399,995
Median ask	\$399,995
This car	\$419,900

Same model year · 1 live listings · as of 29 Oct 2026

OTHER 2023 ROLLS-ROYCE CULLINAN LISTINGS [5]

Oakville, ON · 39,046 km \$399,995

§4 EVENTS

2023	Model year 2023 ^[1] Assembly plant Goodwood, England
15 Aug 2024	Transport Canada recall 2024544 ^[2] Issued for the model year · Label
12 Mar 2026	Transport Canada recall 2026113 ^[2] Issued for the model year · Structure
28 Oct 2026	Listed for sale, Montréal, QC ^[5] Rolls-Royce Motor Cars Quebec · asking \$419,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 1 live listings, as of 29 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 29 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

