

Register entry, as of 27 October 2026

Listed for sale

Record ID b334aabdade0

2018 Buick Regal Essence

2.0 L, 4 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

W04 GR6SX 4 J 1 067224

WMI 1-3

Buick · ADAM OPEL AG

DESCRIPTOR 4-8

Regal · 2.0 L

CHECK 9

Computes

YEAR 10

2018

PLANT 11

Russelsheim

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	2.0 L, 4 cylinders
Make	Buick	Fuel	Gasoline
Model	Regal	Drive	AWD
Trim	Essence	Maker	ADAM OPEL AG
Body	Sedan	Plant	Russelsheim, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/buick/regal/2018

3 recalls listed by Transport Canada for this model year

Brakes

2022347 30 Jun 2022

Issue: On certain vehicles, the electronic brake boost may not work properly when there is a partial or full loss of vacuum-brake assist. As a result, the vehicle may not meet the stopping-distance requirements of Canadian regulations. Safety Risk: An increase in stopping distance could increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct you to take your vehicle to a dealership to update the electronic brake control module (EBCM) software.

Label

2021151 15 Mar 2021

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. General Motors has corrected the tire and loading information label for all new vehicles.

Seats and restraints

2018177 12 Apr 2018

On certain vehicles, the rear outboard seats may have had seat belts improperly routed around the rear seat bolster bracket during the manufacturing process. In the event of a crash, improperly routed seat belts may not provide adequate restraint to the seat occupants which could increase the risk of injury. Correction: Dealers will inspect the rear outboard seat belts for proper routing and reroute the seat belts as necessary.

Listed for the model year, not checked against your VIN. Buick confirms which apply.

Check your VIN with Buick Canada or call a Buick dealer with your VIN.


www.buick.ca/en/ownercenter/recalls



United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$15,995^[5], the median^[4].



Same model year · 1 live listings · as of 27 Oct 2026

§4 EVENTS

2018	Model year 2018 ^[1] Assembly plant Russelsheim, Germany
12 Apr 2018	Transport Canada recall 2018177 ^[2] Issued for the model year · Seats and restraints
15 Mar 2021	Transport Canada recall 2021151 ^[2] Issued for the model year · Label
30 Jun 2022	Transport Canada recall 2022347 ^[2] Issued for the model year · Brakes
24 Oct 2026	Listed for sale, Victoriaville, QC ^[5] Dubois Et Frères & Méthot GM · asking \$15,995
27 Oct 2026	Listing last updated ^[5] asking \$15,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

