Register entry, as of 29 October 2026 Listed for sale Record ID 1847283b59b6

# 2023 Mercedes-Benz E-Class AMG E53

3.0 L, 6 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| W1K | 1J6BB | 3 | P | F | 191994 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Mercedes-Benz Cars | E-Class · 3.0 L | Computes | 2023 | Germany | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2023 | Engine | 3.0 L, 6 cylinders |
| Make | Mercedes-Benz | Fuel | Gasoline |
| Model | E-Class | Drive | Not in the decode |
| Trim | AMG E53 | Maker | Mercedes-Benz Cars |
| Body | Coupe | Plant | Germany |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/e-class/2023

**7** recalls listed by Transport Canada for this model year

### Electrical — 2025213 — 17 Apr 2025

Issue: On certain vehicles, the recall repairs completed by a Mercedes-Benz dealer during recall 8297011 (Transport Canada recall no. 2024-105) may not have been done correctly. As a result, a second repair is required. On certain vehicles, the 80 A fuse may not have been manufactured properly. As a result, the fuse could overheat and fail. If this happens, there could be a sudden loss of power to the wheels. This could also cause the instrument cluster not to work. Safety Risk: A fuse and wiring that overheats can create the risk of a fire. A sudden loss of power to the wheels could increase the risk of a crash. Warnings, tell-tales and gauges that don't display could also increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the main fuse box.

### Electrical — 2024615 — 18 Oct 2024

Issue: On certain vehicles equipped with 4-wheel drive (4Matic), the transmission wiring harness may not be routed correctly. As a result, water could enter the wiring harness connector and cause a short circuit. Note: This recall is an expansion of Transport Canada recall no. 2024-342. Safety Risk: A short circuit can create the risk of a fire, even while the vehicle is parked and turned off. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the transmission wiring harness.

### Electrical — 2024105 — 16 Feb 2024

Issue: On certain vehicles, the 80 A fuse may not have been manufactured properly. As a result, the fuse could overheat and fail. If this happens, there could be a sudden loss of power to the wheels. This could also cause the instrument cluster not to work. Safety Risk: A fuse and wiring that overheats can create the risk of a fire. A sudden loss of power to the wheels could increase the risk of a crash. Warnings, tell-tales and gauges that don't display could also increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the main fuse box.

### Electrical

2024081 9 Feb 2024

Issue: On certain vehicles, the bolt for the 48 V ground connection may not have been tightened properly. As a result, the wiring could overheat and melt. Safety Risk: Wiring that overheats and melts can create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the ground connection.

### Fuel system

2023672 15 Dec 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall 2023-353. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

### Other

2023448 11 Aug 2023

Issue: On certain vehicles, the exit warning feature may not work properly. As a result, a person leaving the vehicle may not get a warning while opening their door in certain traffic situations where another vehicle is approaching from behind. Safety Risk: Opening a door while a vehicle is approaching from behind could create an increased risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to update the multimode radar software.

1 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/e-class/2023

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

## §3 VALUE [3]

This car asks $60,880[4], $1,442 over the median of $59,438[3].




| | |
|---|---|
| Lowest ask | $39,980 |
| Middle half | $52,998 – $74,218 |
| Median ask | $59,438 |
| This car | $60,880 |

Same model year · 16 live listings · as of 29 Oct 2026

OTHER 2023 MERCEDES-BENZ E-CLASS LISTINGS [4]

| | |
|---|---|
| Calgary, AB · 39,701 km | $54,697 |
| Westbank, BC · 20,950 km | $149,999 |
| North York, ON · 97,282 km | $39,980 |
| Saint-Nicolas (Québec) Canada, QC · 30,058 km | $86,987 |
| Mississauga, ON · 95,856 km | $43,495 |
| Montréal-Est, QC · 21,111 km | $89,990 |

## §4 EVENTS

2023 Model year 2023[1]
Assembly plant Germany

| | |
|---|---|
| 23 Jun 2023 | Transport Canada recall 2023353[2]<br>Issued for the model year · Fuel system |
| 11 Aug 2023 | Transport Canada recall 2023448[2]<br>Issued for the model year · Other |
| 15 Dec 2023 | Transport Canada recall 2023672[2]<br>Issued for the model year · Fuel system |
| 9 Feb 2024 | Transport Canada recall 2024081[2]<br>Issued for the model year · Electrical |
| 16 Feb 2024 | Transport Canada recall 2024105[2]<br>Issued for the model year · Electrical |
| 18 Oct 2024 | Transport Canada recall 2024615[2]<br>Issued for the model year · Electrical |
| 17 Apr 2025 | Transport Canada recall 2025213[2]<br>Issued for the model year · Electrical |
| 17 Sep 2026 | Listed for sale, Dollard-des-Ormeaux, QC[4]<br>Mercedes-Benz West-Island (Sub-Prime) · asking $60,880 |
| 29 Oct 2026 | Listing last updated[4]<br>asking $60,880 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same model year, 16 live listings, as of 29 Oct 2026
[4] Live public dealer listings on Cardog, as of 29 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.