Register entry, as of 27 October 2026 Listed for sale Record ID 18e59bbd8493

2020 Mercedes-Benz E-Class E450-4M

3.0 L, 6 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

W1K	1J6JB	X	L	F	135904
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Mercedes-Benz Cars	E-Class · 3.0 L	Computes	2020	Germany	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	3.0 L, 6 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	E-Class	Drive	Not in the decode
Trim	E450-4M	Maker	Mercedes-Benz Cars
Body	Coupe	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/e-class/2020

16 recalls listed by Transport Canada for this model year

Powertrain

2026168 2 Apr 2026

Issue: On certain vehicles, the driveshaft may not have been manufactured properly. Over time, the driveshaft could wear and the universal joint could break. If this happens, there could be a loss of power to the wheels. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the driveshaft.

Electrical

2024342 14 Jun 2024

Issue: On certain vehicles, the recall repairs completed by a Mercedes-Benz dealer during recall 5491309 (Transport Canada recall no. 2022-397) may not have been done correctly. As a result, a second repair is required. On certain vehicles equipped with 4-wheel drive (4Matic), the transmission wiring harness may not be routed correctly. As a result, water could enter the wiring harness connector and cause a short circuit. Note: This recall replaces Transport Canada recall no. 2022-397. Safety Risk: A short circuit can create the risk of a fire, even while the vehicle is parked and turned off. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the transmission wiring harness.

Electrical

2022547 29 Sep 2022

Issue: On certain vehicles, the 12 V battery (in the trunk) could move in a crash. As a result, the battery electrical connexions could detach. If this happens, the post-crash safety systems (like the emergency calling (eCall) system, electric seat adjustment, hazard warning lights, and automatic door unlocking) may not work. Safety Risk: Safety systems that don't work correctly could increase the risk of injury. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to add a bracket to better secure the battery.

Electrical

2022397 22 Jul 2022

Issue: On certain vehicles equipped with 4-wheel drive (4Matic), the transmission wiring harness might not be routed correctly. As a result, water could enter the wiring harness connector and cause a short circuit. Safety Risk: A short circuit can create the risk of a fire, even while the vehicle is parked and turned off. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the connector on the transmission wiring harness, and repair it if necessary. Additionally, the dealer will install a bracket to improve the routing of the transmission wiring harness.

Lights and instruments

2022386 21 Jul 2022

Issue: On a small number of vehicles, a software problem could cause the instrument cluster to reset while driving. This can cause the lighting to turn off momentarily and some warnings may not be visible for a short time. Canadian regulations require the instrument cluster to be illuminated when the headlights are turned on and require warnings to work at all times. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. Mercedes-Benz has made changes to correct this issue on all new vehicles.

Other

2022263 20 May 2022

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the SIM card for the communications module could disable itself. If this happens, the eCall system would not work properly when there is a crash or when the SOS button is pressed. Safety Risk: If the eCall system does not work in an emergency situation, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

10 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/e-class/2020

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $38,552[4], $1,378 under the median of $39,930[3].

Lowest ask	$28,995
Middle half	$33,861 – $57,995
Median ask	$39,930
This car	$38,552

Same model year · 18 live listings · as of 27 Oct 2026

OTHER 2020 MERCEDES-BENZ E-CLASS LISTINGS [4]

Peterborough, ON · 58,170 km	$64,411
Komoka, ON · 109,273 km	$28,995
Oakville, ON · 76,279 km	$34,995
Toronto, ON · 0 km	$30,988
North York, ON · 100,037 km	$32,985
Toronto, ON · 86,275 km	$33,495

§4 EVENTS

2020	Model year 2020[1] Assembly plant Germany
23 Jul 2019	Transport Canada recall 2019357[2] Issued for the model year · Brakes
9 Jun 2020	Transport Canada recall 2020253[2] Issued for the model year · Seats and restraints
22 Jun 2020	Transport Canada recall 2020282[2] Issued for the model year · Engine
10 Nov 2020	Transport Canada recall 2020534[2] Issued for the model year · Seats and restraints
1 Feb 2021	Transport Canada recall 2021041[2] Issued for the model year · Accessories
12 Feb 2021	Transport Canada recall 2021064[2] Issued for the model year · Electrical
3 Mar 2021	Transport Canada recall 2021112[2] Issued for the model year · Other
26 Mar 2021	Transport Canada recall 2021185[2] Issued for the model year · Electrical
14 May 2021	Transport Canada recall 2021291[2] Issued for the model year · Visual system
13 Dec 2021	Transport Canada recall 2021755[2] Issued for the model year · Fuel system
20 May 2022	Transport Canada recall 2022263[2] Issued for the model year · Other
21 Jul 2022	Transport Canada recall 2022386[2] Issued for the model year · Lights and instruments
22 Jul 2022	Transport Canada recall 2022397[2] Issued for the model year · Electrical
29 Sep 2022	Transport Canada recall 2022547[2] Issued for the model year · Electrical
14 Jun 2024	Transport Canada recall 2024342[2] Issued for the model year · Electrical
2 Apr 2026	Transport Canada recall 2026168[2] Issued for the model year · Powertrain
10 Oct 2026	Listed for sale, Mississauga, ON[4] Bos Auto Corporation · asking $38,552

27 Oct 2026	Listing last updated[4] asking $38,552

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same model year, 18 live listings, as of 27 Oct 2026

[4] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.