

Register entry, as of 28 October 2026

Listed for sale

Record ID 706547503c3a

2020 Mercedes-Benz A-Class AMG A35

2.0 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

W1K 3G5BB 7 L J 231860

WMI 1-3

Mercedes-Benz Cars

DESCRIPTOR 4-8

A-Class · 2.0 L

CHECK 9

Computes

YEAR 10

2020

PLANT 11

Germany

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	2.0 L, 4 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	A-Class	Drive	Not in the decode
Trim	AMG A35	Maker	Mercedes-Benz Cars
Body	Sedan	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/a-class/2020

11 recalls listed by Transport Canada for this model year

Structure

2026364 24 Jul 2026

Issue: On certain vehicles, moisture could enter the driver-side door lock microswitch and cause it to corrode. As a result, the microswitch may fail to automatically engage the parking brake and/or the auto park feature when the door is opened. If this happens, the vehicle could roll away. Note: This problem could also cause the radio and/or interior lights to remain on after exiting the vehicle. Safety Risk: A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: To reduce the safety risk, Mercedes-Benz recommends that you should always use the parking brake when you park. Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-side door lock.

Other

2022263 20 May 2022

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the SIM card for the communications module could disable itself. If this happens, the eCall system would not work properly when there is a crash or when the SOS button is pressed. Safety Risk: If the eCall system does not work in an emergency situation, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

Visual system

2022177 12 Apr 2022

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the rearview camera software.



Steering

2021772 17 Dec 2021

Issue: On certain vehicles, the front subframe could corrode over time. If this happens, suspension or steering parts could eventually detach from it. This could affect steering control. Safety Risk: A loss of steering control could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the front subframe (integral carrier) and replace it, if necessary.

Fuel system

2021755 13 Dec 2021

Issue: On certain vehicles, small particles could damage the seals between the fuel rail and fuel injectors. If this happens, there could be a fuel leak in the engine compartment. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel rail and fuel injectors.

Lights and instruments

2021415 5 Jul 2021


Issue: On certain vehicles, a label on the headlamp assembly may contain incorrect information for a service technician. As a result, the headlamps may not get adjusted correctly after a repair. This could cause glare and/or confusion for oncoming drivers. Note: This recall only affects certain vehicles equipped with LED headlamps. Safety Risk: Headlamps that cause glare or confusion for oncoming drivers could increase the risk of a crash. Corrective Action: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the headlamps.

5 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/a-class/2020

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks \$30,995^[4], \$5,625 over the median of \$25,370^[3].



Lowest ask	\$19,795
Middle half	\$21,488 – \$28,745
Median ask	\$25,370
This car	\$30,995

Same model year · 18 live listings · as of 28 Oct 2026

OTHER 2020 MERCEDES-BENZ A-CLASS LISTINGS [4]

London, ON · 132,000 km	\$19,991
Mississauga, ON · 35,433 km	\$25,552
London, ON · 144,078 km	\$19,995
Saint-Nicolas (Québec) Canada, QC · 87,002 km	\$21,987
Calgary, AB · 52,817 km	\$28,995
Richmond, BC · 81,368 km	\$22,995

§4 EVENTS

2020

Model year 2020^[1]
Assembly plant Germany



2 Oct 2019	Transport Canada recall 2019484 ^[2] Issued for the model year · Airbag
14 Feb 2020	Transport Canada recall 2020062 ^[2] Issued for the model year · Lights and instruments
23 Oct 2020	Transport Canada recall 2020507 ^[2] Issued for the model year · Lights and instruments
12 Feb 2021	Transport Canada recall 2021064 ^[2] Issued for the model year · Electrical
14 May 2021	Transport Canada recall 2021291 ^[2] Issued for the model year · Visual system
5 Jul 2021	Transport Canada recall 2021415 ^[2] Issued for the model year · Lights and instruments
13 Dec 2021	Transport Canada recall 2021755 ^[2] Issued for the model year · Fuel system
17 Dec 2021	Transport Canada recall 2021772 ^[2] Issued for the model year · Steering
12 Apr 2022	Transport Canada recall 2022177 ^[2] Issued for the model year · Visual system
20 May 2022	Transport Canada recall 2022263 ^[2] Issued for the model year · Other
24 Jul 2026	Transport Canada recall 2026364 ^[2] Issued for the model year · Structure
26 Oct 2026	Listed for sale, Quebec, QC ^[4] baillargeonauto.com · asking \$30,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [3] Cardog market quote, same model year, 18 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [4] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

