Register entry, as of 29 October 2026 Listed for sale Record ID e69674bb36e9

2021 Mercedes-Benz S-Class S580-4M

4.0 L, 8 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

W1K	6G7GB	0	M	A	028473
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Mercedes-Benz Cars	S-Class · 4.0 L	Computes	2021	Germany	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	4.0 L, 8 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	S-Class	Drive	Not in the decode
Trim	S580-4M	Maker	Mercedes-Benz Cars
Body	Sedan	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/s-class/2021

13 recalls listed by Transport Canada for this model year

Other — 2024641 — 25 Oct 2024

Issue: On a small number of vehicles, a software problem could cause the emergency calling (eCall) system not to work properly when there's a crash or when the SOS button is pressed. Safety Risk: If the eCall system doesn't work in an emergency situation, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to update the communication module software.

Fuel system — 2023672 — 15 Dec 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall 2023-353. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Fuel system — 2023353 — 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Structure

2023169 24 Mar 2023

Issue: On a small number of vehicles, the engine compartment firewall may not be sealed correctly. This could allow water to leak inside the vehicle. If this happens, electrical components could short circuit. This could also affect the Pre-Safe system or cause the vehicle not to start. Note: If this issue is present in your vehicle, you may notice wet carpets in the driver or passenger footwell and fogged windows. Safety Risk: A short circuit could cause emergency systems not to work, which could increase the risk of injuries in a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to reseal the front wall.

Visual system

2022367 8 Jul 2022

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the MBUX multimedia system software.

Other

2022263 20 May 2022

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the SIM card for the communications module could disable itself. If this happens, the eCall system would not work properly when there is a crash or when the SOS button is pressed. Safety Risk: If the eCall system does not work in an emergency situation, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

7 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/s-class/2021

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $85,770[4], the median[3].



Lowest ask	$77,895
Middle half	$83,900 – $99,990
Median ask	$85,770
This car	$85,770

Same configuration · 9 live listings · as of 29 Oct 2026

OTHER 2021 MERCEDES-BENZ S-CLASS LISTINGS [4]

Oakville, ON · 85,000 km	$84,995
North York, ON · 40,537 km	$94,980
Calgary, AB · 33,606 km	$99,990
Ontario, ON · 92,600 km	$79,999

§4 EVENTS

2021 Model year 2021[1]
Assembly plant Germany

1 Feb 2021	Transport Canada recall 2021041[2] Issued for the model year · Accessories
12 Feb 2021	Transport Canada recall 2021064[2] Issued for the model year · Electrical
14 Sep 2021	Transport Canada recall 2021559[2] Issued for the model year · Fuel system
12 Oct 2021	Transport Canada recall 2021624[2] Issued for the model year · Airbag
4 Mar 2022	Transport Canada recall 2022101[2] Issued for the model year · Airbag
18 Mar 2022	Transport Canada recall 2022126[2] Issued for the model year · Lights and instruments
25 Mar 2022	Transport Canada recall 2022140[2] Issued for the model year · Accessories
20 May 2022	Transport Canada recall 2022263[2] Issued for the model year · Other
8 Jul 2022	Transport Canada recall 2022367[2] Issued for the model year · Visual system
24 Mar 2023	Transport Canada recall 2023169[2] Issued for the model year · Structure
23 Jun 2023	Transport Canada recall 2023353[2] Issued for the model year · Fuel system
15 Dec 2023	Transport Canada recall 2023672[2] Issued for the model year · Fuel system
25 Oct 2024	Transport Canada recall 2024641[2] Issued for the model year · Other
18 Sep 2025	Listed for sale, Mont-royal, QC[4] Location Prime Leasing · asking $85,770
29 Oct 2026	Listing last updated[4] asking $85,770

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same configuration, 9 live listings, as of 29 Oct 2026

[4] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.