Register entry, as of 28 October 2026 Listed for sale Record ID 73dd7b3f9276

2022 Mercedes-Benz S-Class S580 MAYBACH

4.0 L, 8 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

W1K	6X7GB	6	N	A	117675
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz Cars	S-Class · 4.0 L	Computes	2022	Germany	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	4.0 L, 8 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	S-Class	Drive	Not in the decode
Trim	S580 MAYBACH	Maker	Mercedes-Benz Cars
Body	Sedan	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/s-class/2022

8 recalls listed by Transport Canada for this model year

Fuel system
2023672 15 Dec 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall 2023-353. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Fuel system
2023353 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Brakes
2023290 17 May 2023

Issue: On certain vehicles, a software problem for the electronic stability control system (ESP) could cause the antilock brake system (ABS), acceleration slip regulation (ASR) and electronic brake force distribution (EBD) to malfunction. Also, the speedometer could display 0 km/h while the vehicle is moving. Note: This problem would cause various warnings to display on the instrument cluster. Safety Risk: An electronic stability control system that doesn't work properly could increase the risk of a crash. Additionally, driving a vehicle without a speedometer could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail. The corrective actions for this recall are under development.

Visual system

2022367 8 Jul 2022

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the MBUX multimedia system software.

Other

2022263 20 May 2022

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the SIM card for the communications module could disable itself. If this happens, the eCall system would not work properly when there is a crash or when the SOS button is pressed. Safety Risk: If the eCall system does not work in an emergency situation, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

Accessories

2022140 25 Mar 2022

Issue: On certain vehicles, the DISTRONIC driver assistance system might not detect when the driver removes their hands from the steering wheel. If the driver has a medical emergency (and is unable to drive or loses consciousness), the active emergency stop assist and emergency call functions would not activate. Note: This recall only affects vehicles equipped with a heated leather steering wheel. Safety Risk: If the active emergency stop and emergency call features do not work in an emergency situation, there could be an increased risk of a crash, and there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the software for the hand detection system.

2 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/s-class/2022

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $195,000[4], $102,005 over the median of $92,995[3].

Lowest ask	$77,999
Middle half	$89,995 – $126,823
Median ask	$92,995
This car	$195,000

Same model year · 9 live listings · as of 28 Oct 2026

OTHER 2022 MERCEDES-BENZ S-CLASS LISTINGS [4]

Montréal, QC · 67,634 km	$168,888
Montréal, QC · 67,634 km	$168,888
Montréal, QC · 37,747 km	$194,888
Oakville, ON · 35,337 km	$89,995
Montréal, QC · 37,747 km	$194,888
Mississauga, ON · 84,393 km	$77,999

§4 EVENTS

2022	Model year 2022[1] Assembly plant Germany
23 Dec 2021	Transport Canada recall 2021788[2] Issued for the model year · Accessories
18 Mar 2022	Transport Canada recall 2022126[2] Issued for the model year · Lights and instruments
25 Mar 2022	Transport Canada recall 2022140[2] Issued for the model year · Accessories
20 May 2022	Transport Canada recall 2022263[2] Issued for the model year · Other
8 Jul 2022	Transport Canada recall 2022367[2] Issued for the model year · Visual system
17 May 2023	Transport Canada recall 2023290[2] Issued for the model year · Brakes
23 Jun 2023	Transport Canada recall 2023353[2] Issued for the model year · Fuel system
15 Dec 2023	Transport Canada recall 2023672[2] Issued for the model year · Fuel system
5 Mar 2025	Listed for sale, Vaughan, ON[4] Marianetti Motors · asking $195,000
28 Oct 2026	Listing last updated[4] asking $195,000

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same model year, 9 live listings, as of 28 Oct 2026

[4] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.